

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/15/2017

Submitted Date:

02/16/2017

Document Number:

678300652

FIELD INSPECTION FORM

Loc ID 442380 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		mike.dinkel@anadarko.com	
, General		COGCCinspections@Anadarko.com	All Inspections, send to Paul Avant as well
Avant, Paul	720-929-6457	Paul.Avant@Anadarko.com	

General Comment:

[inspection of spill/release area.](#)
[Battery at remote location and not inspected at this time, wells on location not subject of this inspection.](#)

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: aqueous liquids, hydrocarbon liquids and gaseous hydrocarbons released during loss of well control event as described in initial form 19 and supplemental form 19 submitted previously with respect to 449004.

Corrective Action: additional information required as part of spill reporting is to Provide documentation of transport of exploration and production wastes to offsite facilities to include the following information:A. The date of the transport; B. The identity of the waste generator; C. The identity of the waste transporter; D. The location of the waste pickup site; E. The type and volume of waste; and F. The name and location of the treatment or disposal site. Date: 05/01/2017

Reportable: YES GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
Anadarko representative Mike Dinkel met me at location. Provided a brief summary of status of sampling and analysis results available to date. Indicated zones where excavation was still needed along line of wells. Suggested operator will submit form 27 for the area where equipment and pipes still need to be removed prior to soil removal. Visual review of some of areas in spill outline are documented as attached photos. 1. well pad 2. area directly along line of wells with cleanup not completed 3. area to north of Adamson pad 4. area to west of Adamson pad 5. vegetative cover in undisturbed area.	gintautp	02/16/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401212979	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4077889
678300653	1. well pad looking northwest	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4077867
678300654	2. still to be remediated	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4077868
678300655	3. area to north of well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4077869
678300656	4. area to west of well location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4077870
678300657	5. present vegetation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4077871