

# Reclamation Inspection

02/22/2017

Operator: Whiting Oil and Gas #96155

Location ID: 431782

Inspection Doc. Number: 682501692

Weld County, CO

NESW Section 27 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Whiting O&G #96155  
Location ID: 431782



**Photo 1:** Photo taken from the south end of the location, facing south. Photo shows additional stormwater and sediment control BMPs have been installed in the interim area.