

Photo#1:

View North over Location Center



Photo#2:

View South over Location Center



February 15, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Windsor Energy PA-University of Texas #24-API#103-09039


Photo#3:

View East over Location Center



Photo#4:

View West over Location Center



February 15, 2017

Photo#5:

View of Access Road at North end of Location



Photo#6:

View of Access Road at South end of Location



February 15, 2017

Photo#7:

West side of Location that borders running ditch/drainage where Vegetation has been grubbed/piled along edge.



February 15, 2017