

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2017

Submitted Date:

03/02/2017

Document Number:

666802958**FIELD INSPECTION FORM**

Loc ID 323866 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211041	WELL	PR	08/27/1993	GW	045-06799	YOUBERG RU 31-12 V	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

1

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Ancillary equipment

2

Comment: [Chemical units at wellhead](#)Corrective Action: Date:

Type: Plunger Lift

1

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

2

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:	<input type="text"/>					Date: <input type="text"/>

PaintCondition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	300 BBLs	STEEL AST		,		
Comment:		Centralized battery					
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	4	300 BBLs	STEEL AST		39.458718,-107.832517		
Comment:							
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:			Date:				
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:			Date:				

Inspected Facilities				
Facility ID: 211041	Type: WELL	API Number: 045-06799	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Ditches	Pass			
		Culverts	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT