

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2017

Submitted Date:

03/02/2017

Document Number:

666802960**FIELD INSPECTION FORM**

Loc ID 334637 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211405	WELL	PR	10/01/1999	GW	045-07165	SAVAGE 1-13	PR
270054	WELL	PR	10/27/2005	GW	045-09443	SAVAGE 1-6B (RBI)	PR
270056	WELL	PR	12/14/2004	GW	045-09444	SAVAGE 1-7A (RB1)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

# 3

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 3

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 3

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	OTHER	STEEL AST		,	
Comment: <a href="#">At separators</a>						
Corrective Action:						Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity) 500gal

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		39.473674,-107.835772	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 211405 Type: WELL API Number: 045-07165 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 270054 Type: WELL API Number: 045-09443 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 270056 Type: WELL API Number: 045-09444 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Seeding	Pass					
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
Berms	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT