

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/15/2017

Submitted Date:

02/15/2017

Document Number:

666802945**FIELD INSPECTION FORM**

Loc ID 336023	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 2 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																							
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1050 17TH STREET #1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80265</u>																																																																																																																											
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Knudson, Dwayne</td> <td>970-456-3335</td> <td>dknudson@ursaresources.com</td> <td><a href="#">All Inspections</a></td> </tr> </table>					Contact Name	Phone	Email	Comment	Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																								
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>																																																																																																																								
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>444198</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23024</td><td>HANGS A 23D-09-06-92</td><td>XX</td></tr> <tr><td>444199</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23025</td><td>HANGS A 34A-09-06-92</td><td>XX</td></tr> <tr><td>444200</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23026</td><td>HANGS A 23C-09-06-92</td><td>XX</td></tr> <tr><td>444201</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23027</td><td>HANGS A 13B-09-06-92</td><td>XX</td></tr> <tr><td>444202</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23028</td><td>HANGS A 24B-09-06-92</td><td>XX</td></tr> <tr><td>444203</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23029</td><td>HANGS A 14A-09-06-92</td><td>XX</td></tr> <tr><td>444204</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23030</td><td>HANGS A 24A-09-06-92</td><td>XX</td></tr> <tr><td>444205</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23031</td><td>HANGS A 33B-09-06-92</td><td>XX</td></tr> <tr><td>444206</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23032</td><td>HANGS A 13C-09-06-92</td><td>XX</td></tr> <tr><td>444207</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23033</td><td>HANGS A 33D-09-06-92</td><td>XX</td></tr> <tr><td>444234</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23034</td><td>HANGS A 33C-09-06-92</td><td>XX</td></tr> <tr><td>444238</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23035</td><td>HANGS A 23B-09-06-92</td><td>XX</td></tr> <tr><td>444239</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23036</td><td>HANGS A 13D-09-06-92</td><td>XX</td></tr> <tr><td>444242</td><td>WELL</td><td>XX</td><td>12/06/2015</td><td>LO</td><td>045-23037</td><td>HANGS A 43A-09-06-92</td><td>XX</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	444198	WELL	XX	12/06/2015	LO	045-23024	HANGS A 23D-09-06-92	XX	444199	WELL	XX	12/06/2015	LO	045-23025	HANGS A 34A-09-06-92	XX	444200	WELL	XX	12/06/2015	LO	045-23026	HANGS A 23C-09-06-92	XX	444201	WELL	XX	12/06/2015	LO	045-23027	HANGS A 13B-09-06-92	XX	444202	WELL	XX	12/06/2015	LO	045-23028	HANGS A 24B-09-06-92	XX	444203	WELL	XX	12/06/2015	LO	045-23029	HANGS A 14A-09-06-92	XX	444204	WELL	XX	12/06/2015	LO	045-23030	HANGS A 24A-09-06-92	XX	444205	WELL	XX	12/06/2015	LO	045-23031	HANGS A 33B-09-06-92	XX	444206	WELL	XX	12/06/2015	LO	045-23032	HANGS A 13C-09-06-92	XX	444207	WELL	XX	12/06/2015	LO	045-23033	HANGS A 33D-09-06-92	XX	444234	WELL	XX	12/06/2015	LO	045-23034	HANGS A 33C-09-06-92	XX	444238	WELL	XX	12/06/2015	LO	045-23035	HANGS A 23B-09-06-92	XX	444239	WELL	XX	12/06/2015	LO	045-23036	HANGS A 13D-09-06-92	XX	444242	WELL	XX	12/06/2015	LO	045-23037	HANGS A 43A-09-06-92	XX
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																				
444198	WELL	XX	12/06/2015	LO	045-23024	HANGS A 23D-09-06-92	XX																																																																																																																				
444199	WELL	XX	12/06/2015	LO	045-23025	HANGS A 34A-09-06-92	XX																																																																																																																				
444200	WELL	XX	12/06/2015	LO	045-23026	HANGS A 23C-09-06-92	XX																																																																																																																				
444201	WELL	XX	12/06/2015	LO	045-23027	HANGS A 13B-09-06-92	XX																																																																																																																				
444202	WELL	XX	12/06/2015	LO	045-23028	HANGS A 24B-09-06-92	XX																																																																																																																				
444203	WELL	XX	12/06/2015	LO	045-23029	HANGS A 14A-09-06-92	XX																																																																																																																				
444204	WELL	XX	12/06/2015	LO	045-23030	HANGS A 24A-09-06-92	XX																																																																																																																				
444205	WELL	XX	12/06/2015	LO	045-23031	HANGS A 33B-09-06-92	XX																																																																																																																				
444206	WELL	XX	12/06/2015	LO	045-23032	HANGS A 13C-09-06-92	XX																																																																																																																				
444207	WELL	XX	12/06/2015	LO	045-23033	HANGS A 33D-09-06-92	XX																																																																																																																				
444234	WELL	XX	12/06/2015	LO	045-23034	HANGS A 33C-09-06-92	XX																																																																																																																				
444238	WELL	XX	12/06/2015	LO	045-23035	HANGS A 23B-09-06-92	XX																																																																																																																				
444239	WELL	XX	12/06/2015	LO	045-23036	HANGS A 13D-09-06-92	XX																																																																																																																				
444242	WELL	XX	12/06/2015	LO	045-23037	HANGS A 43A-09-06-92	XX																																																																																																																				

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444198	WELL	XX	12/06/2015	LO	045-23024	HANGS A 23D-09-06-92	XX
444199	WELL	XX	12/06/2015	LO	045-23025	HANGS A 34A-09-06-92	XX
444200	WELL	XX	12/06/2015	LO	045-23026	HANGS A 23C-09-06-92	XX
444201	WELL	XX	12/06/2015	LO	045-23027	HANGS A 13B-09-06-92	XX
444202	WELL	XX	12/06/2015	LO	045-23028	HANGS A 24B-09-06-92	XX
444203	WELL	XX	12/06/2015	LO	045-23029	HANGS A 14A-09-06-92	XX
444204	WELL	XX	12/06/2015	LO	045-23030	HANGS A 24A-09-06-92	XX
444205	WELL	XX	12/06/2015	LO	045-23031	HANGS A 33B-09-06-92	XX
444206	WELL	XX	12/06/2015	LO	045-23032	HANGS A 13C-09-06-92	XX
444207	WELL	XX	12/06/2015	LO	045-23033	HANGS A 33D-09-06-92	XX
444234	WELL	XX	12/06/2015	LO	045-23034	HANGS A 33C-09-06-92	XX
444238	WELL	XX	12/06/2015	LO	045-23035	HANGS A 23B-09-06-92	XX
444239	WELL	XX	12/06/2015	LO	045-23036	HANGS A 13D-09-06-92	XX
444242	WELL	XX	12/06/2015	LO	045-23037	HANGS A 43A-09-06-92	XX

**General Comment:**  
[inspection is for wells with status of XX, Drilling permits expire 12/05/2017,](#)

**Inspected Facilities**

Facility ID: <u>444198</u>	Type: <u>WELL</u>	API Number: <u>045-23024</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444199</u>	Type: <u>WELL</u>	API Number: <u>045-23025</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444200</u>	Type: <u>WELL</u>	API Number: <u>045-23026</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444201</u>	Type: <u>WELL</u>	API Number: <u>045-23027</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444202</u>	Type: <u>WELL</u>	API Number: <u>045-23028</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444203</u>	Type: <u>WELL</u>	API Number: <u>045-23029</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444204</u>	Type: <u>WELL</u>	API Number: <u>045-23030</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444205</u>	Type: <u>WELL</u>	API Number: <u>045-23031</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444206</u>	Type: <u>WELL</u>	API Number: <u>045-23032</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444207</u>	Type: <u>WELL</u>	API Number: <u>045-23033</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444234</u>	Type: <u>WELL</u>	API Number: <u>045-23034</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444238</u>	Type: <u>WELL</u>	API Number: <u>045-23035</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444239</u>	Type: <u>WELL</u>	API Number: <u>045-23036</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>444242</u>	Type: <u>WELL</u>	API Number: <u>045-23037</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401220630	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4086255">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4086255</a>