

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/24/2017

Submitted Date:

02/27/2017

Document Number:

672500416**FIELD INSPECTION FORM**

Loc ID 448368	Inspector Name: Gomez, Jason	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	---------------------------------	---	-------------------	--

Operator Information:OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 1625 BROADWAY SUITE 300City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, Dave		dpennington@syrinfo.com	Synergy Inspection
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448712	WELL	DG	12/18/2016		123-43967	Orr State 25N-35B-M	DG
448713	WELL	DG	12/17/2016		123-43968	Orr State 25C-35-M	DG
448714	WELL	DG	01/11/2017		123-43969	Orr State 23N-35C-M	DG
448715	WELL	DG	01/15/2017		123-43970	Orr State 10N-35A-M	DG
448716	WELL	DG	01/12/2017		123-43971	Orr State 10C-35-M	DG
448717	WELL	DG	01/16/2017		123-43972	Orr State 10N-35C-M	DG
448720	WELL	DG	01/09/2017		123-43973	Orr State 15N-35B-M	DG
448721	WELL	DG	01/10/2017		123-43974	Orr State 23C-35-M	DG
448722	WELL	DG	01/08/2017		123-43975	Orr State 15C-35-M	DG
448723	WELL	DG	01/07/2017		123-43976	Orr State 36N-35B-M	DG
448724	WELL	DG	01/06/2017		123-43977	Orr State 36C-35-M	DG
448732	WELL	DG	01/05/2017		123-43978	Orr State 36N-35C-M	DG
448733	WELL	DG	12/19/2016		123-43979	Orr 25C-32-M	DG
448734	WELL	DG	12/26/2016		123-43980	Orr 11N-32C-M	DG
448735	WELL	DG	12/27/2016		123-43981	Orr 11C-32-M	DG
448736	WELL	DG	12/20/2016		123-43982	Orr 25N-32B-M	DG
448737	WELL	DG	12/29/2016		123-43983	Orr 23C-32-M	DG
448738	WELL	DG	12/28/2016		123-43984	Orr 11N-32B-M	DG
448742	WELL	DG	12/30/2016		123-43985	Orr 23N-32B-M	DG
448743	WELL	DG	01/01/2017		123-43986	Orr 14N-32C-M	DG
448744	WELL	DG	12/31/2016		123-43987	Orr 23N-32A-M	DG
448745	WELL	DG	01/04/2017		123-43988	Orr 36C-32-M	DG
448746	WELL	DG	01/03/2017		123-43989	Orr 36N-32B-M	DG

448747	WELL	DG	01/02/2017		123-43990	Orr 14C-32-M	DG
--------	------	----	------------	--	-----------	--------------	----

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

#

Comment: approx 32' sound wall on on east, south and west end of location

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Field Flare

Comment: 2 Field Flares on location not in use at time of inspection

Corrective Action:

Date:

Facility ID: <u>448713</u>	Type: <u>WELL</u>	API Number: <u>123-43968</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448714</u>	Type: <u>WELL</u>	API Number: <u>123-43969</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448715</u>	Type: <u>WELL</u>	API Number: <u>123-43970</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448716</u>	Type: <u>WELL</u>	API Number: <u>123-43971</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448717</u>	Type: <u>WELL</u>	API Number: <u>123-43972</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448720</u>	Type: <u>WELL</u>	API Number: <u>123-43973</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448721</u>	Type: <u>WELL</u>	API Number: <u>123-43974</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448722</u>	Type: <u>WELL</u>	API Number: <u>123-43975</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448723</u>	Type: <u>WELL</u>	API Number: <u>123-43976</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448724</u>	Type: <u>WELL</u>	API Number: <u>123-43977</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448732</u>	Type: <u>WELL</u>	API Number: <u>123-43978</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448733</u>	Type: <u>WELL</u>	API Number: <u>123-43979</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

Well Drilling

Rig: Rig Name: Precision 462 Pusher/Rig Manager: Larry Schneider
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: _____

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: <u>448734</u>	Type: <u>WELL</u>	API Number: <u>123-43980</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>448735</u>	Type: <u>WELL</u>	API Number: <u>123-43981</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>

Facility ID:	448736	Type:	WELL	API Number:	123-43982	Status:	DG	Insp. Status:	DG
Facility ID:	448737	Type:	WELL	API Number:	123-43983	Status:	DG	Insp. Status:	DG
Facility ID:	448738	Type:	WELL	API Number:	123-43984	Status:	DG	Insp. Status:	DG
Facility ID:	448742	Type:	WELL	API Number:	123-43985	Status:	DG	Insp. Status:	DG
Facility ID:	448743	Type:	WELL	API Number:	123-43986	Status:	DG	Insp. Status:	DG
Facility ID:	448744	Type:	WELL	API Number:	123-43987	Status:	DG	Insp. Status:	DG
Facility ID:	448745	Type:	WELL	API Number:	123-43988	Status:	DG	Insp. Status:	DG
Facility ID:	448746	Type:	WELL	API Number:	123-43989	Status:	DG	Insp. Status:	DG
Facility ID:	448747	Type:	WELL	API Number:	123-43990	Status:	DG	Insp. Status:	DG

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Waddles	Pass					
Sediment Traps						
Berms	Pass			Material Handling And Spill Prevention	Pass	
Silt Fences	Pass					
Ditches	Pass			Vehicle Tracking	Fail	
Culverts	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401221198	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4086715