

**Inspection Photos**  
**Location Name: Bashor 18-1**  
**API: 05-123-12452**



**Photo from prior inspection for comparison purposes**



**Photo 1: Berms repaired**

**Inspection Photos**  
**Location Name: Bashor 18-1**  
**API: 05-123-12452**



**Photo from prior inspection for comparison purposes**



**Photo 2: Tank labeled**

**Inspection Photos**  
**Location Name: Bashor 18-1**  
**API: 05-123-12452**



**Photo from prior inspection for comparison purposes**



**Photo 3: Stained soil removed**

**Inspection Photos**  
**Location Name: Bashor 18-1**  
**API: 05-123-12452**



**Photo from prior inspection for comparison purposes**



**Photo 4: Stained soil removed**

**Inspection Photos**  
**Location Name: Bashor 18-1**  
**API: 05-123-12452**



**Photo from prior inspection for comparison purposes**



**Photo 5: Deadman marked**



**Inspection Photos**  
**Location Name: Bashor 18-1**  
**API: 05-123-12452**



**Photo 6: Debris in separator shack**



**Photo 7: Debris in separator shack**

**Inspection Photos**  
**Location Name: Bashor 18-1**  
**API: 05-123-12452**



**Photo 8: Debris near separator shack**