

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/10/2017

Submitted Date:

03/10/2017

Document Number:

675203991**FIELD INSPECTION FORM**
 Loc ID 312718 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279895	WELL	PR	12/01/2013	GW	077-08949	ORCHARD UNIT 15-7 (G15OU)	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	279895	Type:	WELL	API Number:	077-08949	Status:	PR	Insp. Status:	PR

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Retention Ponds	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT