

Photo#1:

Overview Of Location from Entry to NW



March 3, 2017

Photo#2:

View of Location from NW to SE.



March 3, 2017

Photo#3:

Rill erosion; Rock & sediment movement is evident on Cut Slope.

