

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/03/2017

Submitted Date:

03/05/2017

Document Number:

680101556

**FIELD INSPECTION FORM**

Loc ID 446582	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 10447 Name of Operator: URSA OPERATING COMPANY LLC Address: 1050 17TH STREET #1700 City: DENVER State: CO Zip: 80265				<b>Findings:</b> 6 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
		jlind@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446573	WELL	XX	07/14/2016		045-23262	BMC D 32C-18-07-95	CI
446574	WELL	XX	07/14/2016		045-23263	BMC D 44D-07-07-95	CI
446575	WELL	XX	07/14/2016		045-23264	BMC D 41C-18-07-95	CI
446576	WELL	XX	07/14/2016		045-23265	BMC D 41A-18-07-95	CI
446577	WELL	XX	07/14/2016		045-23266	BMC D 34B-07-07-95	CI
446578	WELL	XX	07/14/2016		045-23267	BMC D 31A-18-07-95	CI
446579	WELL	XX	07/14/2016		045-23268	BMC D 34C-07-07-95	CI
446580	WELL	XX	07/14/2016		045-23269	BMC D 32A-18-07-95	CI
446581	WELL	XX	07/14/2016		045-23270	BMC D 32B-18-07-95	CI
446583	WELL	XX	07/14/2016		045-23271	BMC D 31B-18-07-95	CI
446584	WELL	XX	07/14/2016		045-23272	BMC D 32D-18-07-95	CI
446585	WELL	XX	07/14/2016		045-23273	BMC D 34D-07-07-95	CI
446586	WELL	XX	07/14/2016		045-23274	BMC D 32E-18-07-95	CI
446587	WELL	XX	07/14/2016		045-23275	BMC D 34A-07-07-95	CI
446588	WELL	XX	07/14/2016		045-23276	BMC D 31C-18-07-95	CI
446589	WELL	XX	07/14/2016		045-23277	BMC D 31D-18-07-95	CI
446765	WELL	XX	07/20/2016		045-23278	BMC D 41B-18-07-95	CI
447694	WELL	XX	09/09/2016		045-23307	BMC D 11C-18-07-95	CI
447696	WELL	XX	09/09/2016		045-23308	BMC D 12C-18-07-95	CI
447697	WELL	XX	09/09/2016		045-23309	BMC D 11D-18-07-95	CI
447699	WELL	XX	09/09/2016		045-23311	BMC D 12B-18-07-95	CI
447700	WELL	XX	09/09/2016		045-23312	BMC D 12A-18-07-95	CI
447701	WELL	XX	09/10/2016		045-23313	BMC D 21C-18-07-95	CI

447702	WELL	XX	09/10/2016		045-23314	BMC D 22B-18-07-95	CI
447703	WELL	XX	09/10/2016		045-23315	BMC D 22A-18-07-95	CI
447704	WELL	XX	09/10/2016		045-23316	BMC D 21B-18-07-95	CI
447705	WELL	XX	09/10/2016		045-23317	BMC D 21D-18-07-95	CI
447714	WELL	XX	09/10/2016		045-23326	BMC D 22C-18-07-95	CI

**General Comment:**

This is a Construction and Stormwater Inspection. Form 42 (Notice of Construction) has been Filed for this Location; Start Date 2/21/2017. Conditions at time of Inspection were 50 degrees; Sunny with Winds Picking up.

**Location Construction**

Location ID: 446582 CDP: \_\_\_\_\_

Comment: Top Soil Stored at South Side of Location has been applied to South Berm and Tracked alleviating Concerns of Sediment Run-Off. Pipe Line Co has repaired and installed BMPs at Disturbed area in SW Corner that is just outside O&G Loc LOD. Pipe line Activities are shifting slowly to NE of Pad; easing Congestion.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: Water Truck was observed on Location wetting areas between passes by Equipment as Wind was picking up; also noted that Speed of equipment was slowed as Dust Control BMP.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	Yes		

Comments: Erosion BMPs: \_\_\_\_\_  
Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

BERMS	Yes		
-------	-----	--	--

Comments: Erosion BMPs: \_\_\_\_\_  
Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

WADDLES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Better Parking area has been delineated at end of Access Road & Consultation with Pipe Line Co is alleviating problem of Wattles in Access Road Ditch being Run Over Daily.

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

RETENTION PONDS	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

DITCHES	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID: <u>446573</u>	Type: <u>WELL</u>	API Number: <u>045-23262</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446574</u>	Type: <u>WELL</u>	API Number: <u>045-23263</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446575</u>	Type: <u>WELL</u>	API Number: <u>045-23264</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446576</u>	Type: <u>WELL</u>	API Number: <u>045-23265</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446577</u>	Type: <u>WELL</u>	API Number: <u>045-23266</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446578</u>	Type: <u>WELL</u>	API Number: <u>045-23267</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446579</u>	Type: <u>WELL</u>	API Number: <u>045-23268</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446580</u>	Type: <u>WELL</u>	API Number: <u>045-23269</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446581</u>	Type: <u>WELL</u>	API Number: <u>045-23270</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446583</u>	Type: <u>WELL</u>	API Number: <u>045-23271</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446584</u>	Type: <u>WELL</u>	API Number: <u>045-23272</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446585</u>	Type: <u>WELL</u>	API Number: <u>045-23273</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446586</u>	Type: <u>WELL</u>	API Number: <u>045-23274</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446587</u>	Type: <u>WELL</u>	API Number: <u>045-23275</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446588</u>	Type: <u>WELL</u>	API Number: <u>045-23276</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446589</u>	Type: <u>WELL</u>	API Number: <u>045-23277</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>446765</u>	Type: <u>WELL</u>	API Number: <u>045-23278</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447694</u>	Type: <u>WELL</u>	API Number: <u>045-23307</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>447696</u>	Type: <u>WELL</u>	API Number: <u>045-23308</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Facility ID: 447697	Type: WELL	API Number: 045-23309	Status: XX	Insp. Status: CI
Facility ID: 447699	Type: WELL	API Number: 045-23311	Status: XX	Insp. Status: CI
Facility ID: 447700	Type: WELL	API Number: 045-23312	Status: XX	Insp. Status: CI
Facility ID: 447701	Type: WELL	API Number: 045-23313	Status: XX	Insp. Status: CI
Facility ID: 447702	Type: WELL	API Number: 045-23314	Status: XX	Insp. Status: CI
Facility ID: 447703	Type: WELL	API Number: 045-23315	Status: XX	Insp. Status: CI
Facility ID: 447704	Type: WELL	API Number: 045-23316	Status: XX	Insp. Status: CI
Facility ID: 447705	Type: WELL	API Number: 045-23317	Status: XX	Insp. Status: CI
Facility ID: 447714	Type: WELL	API Number: 045-23326	Status: XX	Insp. Status: CI

**COGCC Comments**

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS. Refer to Photos attached for more detail	colbyl	03/05/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401225292	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090496</a>
680101557	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090494">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090494</a>