

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/10/2017

Submitted Date:

03/10/2017

Document Number:

674703724**FIELD INSPECTION FORM**
 Loc ID 322529 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2716 | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 210724 | WELL | PR | 10/01/1994 | GW | 045-06482 | GRAND VALLEY-FEDERAL 1 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |

| | | | | |
|--------------------|--|--|-------|--|
| Comment: | Dehydrator/Separator combo Airs id. 045-1953-001 | | | |
| Corrective Action: | | | Date: | |
| Type: Dehydrator | # 1 | | | |
| Comment: | Dehydrator/Separator combo | | | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|-----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 80 bbls | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | Date: | |

| Inspected Facilities | | | | |
|----------------------|---------------------------------|-----------------------|------------|------------------|
| Facility ID: 210724 | Type: WELL | API Number: 045-06482 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Producing well on plunger lift. | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| | | Ditches | Pass | | | |
| Ditches | Pass | | | | | |
| | | Compaction | Pass | | | |
| Check Dams | Pass | | | | | |
| Gravel | Pass | | | | | |
| | | Culverts | Pass | | | |
| Compaction | Pass | | | | | |
| | | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT