

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401227269

Date Received:

03/10/2017

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

449643

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80217-3779</u>
Contact Person: <u>Paul Schwarz</u>		Mobile: <u>()</u>
		Email: <u>Paul.Schwarz@Anadarko.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401227269

Initial Report Date: 03/07/2017 Date of Discovery: 03/07/2017 Spill Type: Historical Release

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SESE SEC 17 TWP 2N RNG 66W MERIDIAN 6Latitude: 40.132073 Longitude: -104.793805Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY☐ Facility/Location ID No _____☒ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): UnknownEstimated Condensate Spill Volume(bbl): UnknownEstimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): UnknownEstimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LANDOther(Specify): Tank Battery PadWeather Condition: Sunny, 50°FSurface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☒ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

While excavating a nonreportable release at the Nesmith 15-17, UPRR 42 Pan Am AQ True #1 tank battery, historical impacts were encountered beneath the oil tank. Groundwater was encountered in the excavation at approximately 13 feet below ground surface. A groundwater sample (GW01) was collected and submitted for laboratory analysis of BTEX. Laboratory analytical results received on March 7, 2017, indicated petroleum hydrocarbon impact to groundwater. The analytical results and excavation details will be summarized in a supplemental report. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
3/7/2017	Weld County	Roy Rudisill	-	Notified via Email
3/7/2017	Weld County	Troy Swain	-	Notified via Email
3/7/2017	Weld County	Tom Parko	-	Notified via Email
3/7/2017	Landowner	Landowner	-	Notified via Phone

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Paul Schwarz
Title: HSE Representative Date: 03/10/2017 Email: Paul.Schwarz@Anadarko.com

COA Type

Description

	Provide documentation justifying closure request within 90 days of release via supplemental form 19. If investigation and remediation require further actions beyond 90 days then submit form 27 for approval within 90 days of spill (06June2017).
--	---

Attachment Check List

Att Doc Num

Name

401227269	SPILL/RELEASE REPORT(INITIAL)
401227290	OTHER
401229645	TOPOGRAPHIC MAP
401233507	FORM 19 SUBMITTED

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)