

Inspection Photos
Location Name: Battle Mountain 1-29
API: 05-081-06632



Photo 1. View at entrance to location facing south.

Inspection Photos
Location Name: Battle Mountain 1-29
API: 05-081-06632



Photo 2. Staining at loadout.



Photo 3. Possible landfarm area

Inspection Photos
Location Name: Battle Mountain 1-29
API: 05-081-06632



Photo 4. Shed open to wildlife and elements. Container with no label.



Photo 5. Drums stored outside shed with no label or containment.

Inspection Photos
Location Name: Battle Mountain 1-29
API: 05-081-06632



Photo 6. Interior of shed. Drums stored with no label or containment.



Photo 7. Interior of shed.