



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment: <a href="#">Chemical containers at wells</a>		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 7	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 7	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210824	Type:	WELL	API Number:	045-06582	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	272217	Type:	WELL	API Number:	045-10046	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	272219	Type:	WELL	API Number:	045-10044	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	272220	Type:	WELL	API Number:	045-10043	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	272221	Type:	WELL	API Number:	045-10042	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	278043	Type:	WELL	API Number:	045-10826	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	278044	Type:	WELL	API Number:	045-10825	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	278045	Type:	WELL	API Number:	045-10824	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				

--

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Gravel	Pass			
Ditches	Pass					
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	
Waddles	Pass					
		Ditches	Pass			
Gravel	Pass					
		Compaction	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT