

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401235312

Date Received:

03/16/2017

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

449651

## SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>DCP MIDSTREAM LP</u>	Operator No: <u>4680</u>	<b>Phone Numbers</b>
Address: <u>370 17TH STREET - SUITE 2500</u>		Phone: <u>(970) 356-9700</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(970) 373-8905</u>
Zip: <u>80202</u>		Email: <u>bshayes@dcpmidstream.com</u>
Contact Person: <u>Branden Hayes</u>		

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401235312

Initial Report Date: 03/16/2017      Date of Discovery: 03/03/2017      Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSE SEC 15 TWP 2N RNG 67W MERIDIAN 6Latitude: 40.133323 Longitude: -104.873460Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

#### Reference Location:

Facility Type: PIPELINE☐ Facility/Location ID No \_\_\_\_\_☒ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

#### **Fluid(s) Spilled/Released (please answer Yes/No):**

Was one (1) barrel or more spilled outside of berms or secondary containment? No

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): >0 and <1Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### **Land Use:**

Current Land Use: OTHEROther(Specify): Tank BatteryWeather Condition: Warm and clearSurface Owner: OTHER (SPECIFY)Other(Specify): unknown

#### **Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):**

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

DCP Environmental was informed by DCP Pipeline group of a pipeline valve release near a DCP Operated meter run on March 3rd, 2017 around 9:00 am. At the time of discovery a small amount of liquid was present at the soil surface. The DCP Environmental group reviewed the pipeline release along with DCP Pipeline to investigate the release. During the investigation the size of the release was estimated at less than 1 barrel of condensate. DCP Pipeline group repaired the valve on March 3rd, 2017. DCP Environmental collected two soil samples from the impacted area and submitted them for analysis. Cleanup of the released condensate is scheduled, soil samples will be collected and any further remediation will be conducted as needed.

List Agencies and Other Parties Notified:

**OPERATOR COMMENTS:**

eForm is being submitted as a precaution that during remediation of the location it is determined that greater than 1 bbl of condensate had been spilled.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Branden Hayes

Title: Env Specialist Date: 03/16/2017 Email: bshayes@dcpmidstream.com

**COA Type**

**Description**

	Provide documentation justifying closure request within 90 days of release via supplemental form 19. If investigation and remediation require further actions beyond 90 days then submit form 27 for approval within 90 days of spill (02June2017).
--	---

**Attachment Check List**

**Att Doc Num**

**Name**

401235312	SPILL/RELEASE REPORT(INITIAL)
401235417	ANALYTICAL RESULTS
401235541	FORM 19 SUBMITTED

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)