



**Inspected Facilities**

Facility ID: 243527 Type: WELL API Number: 123-11319 Status: PR Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: RANGER

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: YES

Cement Fall Back: YES

Top Job, 1" Volume: YES

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 1006' TO SURFACE

Cement Volume (sx): 489

Good Return During Job: YES

Cement Type: G-NEAT

Comment: CASING CUT @ 900' RIH 100' TO 1006' PUMPED SXS G-NEAT TO SURFACE

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_