

Inspection Photos
Location Name: Gruwell 44-32
API: 05-081-07317



Photo 1. View of location at entrance facing south.



Photo 2. Lube oil stored at wellhead with no secondary containment.