

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2017

Submitted Date:

03/20/2017

Document Number:

666803031**FIELD INSPECTION FORM**

Loc ID 334967 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271628	WELL	PR	08/27/2004	GW	045-09917	BENZEL 36-15D (N36NWB)	PR
271629	WELL	PR	09/13/2004	GW	045-09918	BENZEL 36-11D (N36NWB)	PR
271630	WELL	PR	10/01/2004	GW	045-09919	BENZEL 36-14D (N36NWB)	PR
271631	WELL	PR	08/23/2004	GW	045-09920	BENZEL 1-5D (N36NWB)	PR
272295	WELL	PR	09/09/2004	GW	045-10057	BENZEL 36-11A (N36NWB)	PR
272297	WELL	PR	08/31/2004	GW	045-10058	BENZEL 36-12D (N36NWB)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Vertical Heated Separator

5

Comment: Corrective Action: Date:

Type: Horizontal Heated Separator

1

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date:

Type: Ancillary equipment

0

Comment: Corrective Action: Date:

Type: Plunger Lift

6

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>					Date: <input type="text"/>

PaintCondition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
METHANOL	1	1000 GAL	STEEL AST		,		
Comment:		Centralized battery					
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	500 BBLs	STEEL AST		39.478101,-107.727553		
Comment:							
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:				Date:			
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:				Date:			

Inspected Facilities									
Facility ID:	271628	Type:	WELL	API Number:	045-09917	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	271629	Type:	WELL	API Number:	045-09918	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	271630	Type:	WELL	API Number:	045-09919	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	271631	Type:	WELL	API Number:	045-09920	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	272295	Type:	WELL	API Number:	045-10057	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	272297	Type:	WELL	API Number:	045-10058	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Ditches	Pass					
		Culverts	Pass			
Retention Ponds	Pass					
		Gravel	Pass			
Berms	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT