

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2017

Submitted Date:

03/20/2017

Document Number:

666803032**FIELD INSPECTION FORM**

Loc ID 334944 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256487	WELL	PR	06/01/2002	GW	045-07459	BENZEL 1-11 (N36NW)	PR
256488	WELL	PR	08/10/2000	GW	045-07460	BENZEL 1-10(N36NW)	PR
256489	WELL	PR	06/01/2002	GW	045-07461	BENZEL 36-14 (N36NW)	PR
256490	WELL	PR	06/01/2002	GW	045-07462	BENZEL 36-15(N36NW)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:									
Corrective Action:								Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS		
CONDENSATE		4	300 BBLS	STEEL AST			39.478089,-107.726741		
Comment:									

Corrective Action:		Date:		
Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	256487	Type:	WELL	API Number:	045-07459	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	256488	Type:	WELL	API Number:	045-07460	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	256489	Type:	WELL	API Number:	045-07461	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	256490	Type:	WELL	API Number:	045-07462	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Gravel	Pass					
		Ditches	Pass			
		Culverts	Pass			
		Gravel	Pass			
Ditches	Pass					
Retention Ponds	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT