

Inspection Photos
Location Name: Federal 32-3
Facility ID: 312411



Photo 1. Blowdown pit SE corner 39.323456/ - 109.015419. Taken 8/20/14



Photo 2. Blowdown pit SE corner 39.323456/ - 109.015419. Pit has been closed. Taken 3/21/17

Inspection Photos
Location Name: Federal 32-3
Facility ID: 312411



Photo 3. Blowdown pit SE corner 39.323025/ - 109.015347. Taken 8/20/14



Photo 4. Blowdown pit SE corner 39.323025/ - 109.015347. Pit has been closed. Taken 3/21/17

Inspection Photos
Location Name: Federal 32-3
Facility ID: 312411



Photo 5. Horizontal heated separator. 39.323197/ -109.015442. Taken 8/20/14



Photo 6. Horizontal heated separator has been disconnected and moved to 39.32315/ -109.015831 Taken 3/21/17

Inspection Photos
Location Name: Federal 32-3
Facility ID: 312411



Photo 7. No evidence of well on location