

Inspected Facilities

Facility ID: 251484 Type: WELL API Number: 123-19287 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 6574'

Cement Volume (sx): 2

Good Return During Job: _____

Cement Type: g-neat

Comment: RIH WL SET CIBP @6574' RIH W/DUMP AND DP 2 SXS G NEAT ON CIBP

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401235676	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4100709