

Inspection Photos
Location Name: Bar-X 28-3
Facility ID: 312392



Photo 1. Stuffing box leaking condensate.



Photo 2. Containment under stuffing box.

Inspection Photos
Location Name: Bar-X 28-3
Facility ID: 312392



Photo 3. Staining around containment.



Photo 4. Pump Jack operating at time of inspection.