

Inspection Photos  
Location Name: Gunderson 12-10 Pad  
Facility ID: 334494



**Photo 1. Damaged fence around wellheads. Taken 2/21/17**



**Photo 2. Damaged fence taken at follow up inspection.**