

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2017

Submitted Date:

03/29/2017

Document Number:

675204070

FIELD INSPECTION FORM

Loc ID 422420 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1400
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	
Clark, Chris		cclark@Laramie-Energy.com	
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423247	WELL	PR	05/06/2014	GW	077-10159	Hawxhurst 17-05B	PR
423252	WELL	PR	05/02/2014	GW	077-10160	Hawxhurst 17-03C	PR

General Comment:

Follow up to inspection Doc#671000305. Approved Form 26 Doc#401101507 on file for sources of produced water related to spill. Operator has been in contact with COGCC Environmental staff to close CA related to previous inspection.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date:

Paint

Condition	Adequate	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date:

Venting:

Yes/No	NO	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
		Date:

Flaring:

Type	<input type="text"/>
------	----------------------

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 423247 Type: WELL API Number: 077-10159 Status: PR Insp. Status: PR

Facility ID: 423252 Type: WELL API Number: 077-10160 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass	Culverts	Pass			
Retention Ponds	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT