

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/29/2017

Submitted Date:

03/29/2017

Document Number:

673404372**FIELD INSPECTION FORM**

Loc ID 313019 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 6720Name of Operator: BAYLESS PRODUCER LLC\* ROBERT LAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223370	WELL	PR	06/11/2014	GW	081-06734	BUCK PEAK 34-23 HD	WK

**General Comment:**

**Inspected Facilities**Facility ID: 223370 Type: WELL API Number: 081-06734 Status: PR Insp. Status: WK**Workover**

Comment: Inspector on location to witness MIT. (Form 42 notice document number 401234346).  
5000 PSI chart and gauge for 300 PSI test.  
MIT passed at 300 PSI for 15 minutes. Chart will be sent with Form 21.

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
Inspector on location to witness MIT. (Form 42 notice document number 401234346). 5000 PSI chart and gauge for 300 PSI test. MIT passed at 300 PSI for 15 minutes. Chart will be sent with Form 21.	waldrone	03/29/2017