

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2017

Submitted Date:

03/23/2017

Document Number:

674703765**FIELD INSPECTION FORM**

Loc ID 335235	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211229	WELL	PR	02/10/1997	GW	045-06988	FEDERAL GM 13-35	PR
211230	WELL	PR	09/11/2000	GW	045-06989	FEDERAL DOE 2-M-35	PR
439746	WELL	XX	10/26/2016	LO	045-22578	Federal GM 11-35	ND
439747	WELL	XX	10/26/2016	LO	045-22579	Federal GM 21-35	ND
439748	WELL	XX	10/26/2016	LO	045-22580	Federal GM 323-35	ND
439753	WELL	XX	10/26/2016	LO	045-22581	Federal GM 423-35	ND
439763	WELL	XX	10/26/2016	LO	045-22582	Federal GM 44-34	ND
439771	WELL	XX	10/26/2016	LO	045-22584	Federal GM 513-35	ND
439776	WELL	XX	10/26/2016	LO	045-22585	Federal GM 421-35	ND
439779	WELL	XX	10/26/2016	LO	045-22586	Federal GM 444-34	ND
439786	WELL	XX	10/26/2016	LO	045-22588	Federal GM 321-35	ND
439788	WELL	XX	10/26/2016	LO	045-22589	Federal GM 322-35	ND
439789	WELL	XX	10/26/2016	LO	045-22590	Federal GM 313-35	ND
439790	WELL	XX	10/26/2016	LO	045-22591	Federal GM 312-35	ND

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Type: Dehydrator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	211229	Type:	WELL	API Number:	045-06988	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	211230	Type:	WELL	API Number:	045-06989	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	439746	Type:	WELL	API Number:	045-22578	Status:	XX	Insp. Status:	ND
Facility ID:	439747	Type:	WELL	API Number:	045-22579	Status:	XX	Insp. Status:	ND
Facility ID:	439748	Type:	WELL	API Number:	045-22580	Status:	XX	Insp. Status:	ND
Facility ID:	439753	Type:	WELL	API Number:	045-22581	Status:	XX	Insp. Status:	ND
Facility ID:	439763	Type:	WELL	API Number:	045-22582	Status:	XX	Insp. Status:	ND
Facility ID:	439771	Type:	WELL	API Number:	045-22584	Status:	XX	Insp. Status:	ND
Facility ID:	439776	Type:	WELL	API Number:	045-22585	Status:	XX	Insp. Status:	ND
Facility ID:	439779	Type:	WELL	API Number:	045-22586	Status:	XX	Insp. Status:	ND
Facility ID:	439786	Type:	WELL	API Number:	045-22588	Status:	XX	Insp. Status:	ND
Facility ID:	439788	Type:	WELL	API Number:	045-22589	Status:	XX	Insp. Status:	ND
Facility ID:	439789	Type:	WELL	API Number:	045-22590	Status:	XX	Insp. Status:	ND
Facility ID:	439790	Type:	WELL	API Number:	045-22591	Status:	XX	Insp. Status:	ND

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
Seeding	Fail					
Check Dams	Pass					
Compaction	Pass					
Ditches	Pass					
		Culverts	Pass			
		Compaction	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401241847	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4107200