

Inspection Photos

03/23/2017

Operator: Tindall Operating Co #88380

Location ID: 327507

Inspection Doc. Number: 682501828

Weld County, CO

NESW Section 27 T7N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Tindall Operating
Location ID: 327507



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Tindall Operating
Location ID: 327507



Photo 6: Photo taken from the location facing north. Photo shows vegetation over the reclamation area.



Photo 7: Photo taken from the location facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: Tindall Operating
Location ID: 327507



Photo 4: Photo taken from the location facing south. Photo shows vegetation over the reclamation area.



Photo 5: Photo taken from the location facing west. Photo shows vegetation over the reclamation area.