

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2017

Submitted Date:

03/30/2017

Document Number:

666803071**FIELD INSPECTION FORM**

Loc ID 335505 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sgghan@vnrlc.com	Sr. EH&S
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279431	WELL	PR	03/01/2011	GW	045-11032	JACKSON 44D-28-692	PR
279432	WELL	PR	03/01/2011	GW	045-11033	JACKSON 33C-28-692	SI
279433	WELL	PR	03/01/2011	GW	045-11034	JACKSON 43C-28-692	PR
280246	WELL	PR	02/18/2009	GW	045-11223	JACKSON 34D-28-692	PR
298301	WELL	PR	01/20/2010	GW	045-17117	JACKSON 44C-28-692	PR
298794	WELL	PR	01/13/2010	GW	045-17426	JACKSON 43A-28-692	PR
298795	WELL	PR	01/11/2010	GW	045-17427	JACKSON 33D-28-692	PR
298796	WELL	PR	11/11/2010	GW	045-17428	JACKSON 33A-28-692	PR
298797	WELL	PR	01/13/2010	GW	045-17429	JACKSON 34C-28-692	PR
298798	WELL	PR	01/13/2010	GW	045-17430	JACKSON 44A-28-692	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

10

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

10

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

2

Comment: Chemical units at wellhead

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLS	STEEL AST		39.494142,-107.668258
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	279431	Type:	WELL	API Number:	045-11032	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	279432	Type:	WELL	API Number:	045-11033	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:	last posted production numbers Jan 2016								
Corrective Action:						Date:			
Facility ID:	279433	Type:	WELL	API Number:	045-11034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	280246	Type:	WELL	API Number:	045-11223	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298301	Type:	WELL	API Number:	045-17117	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298794	Type:	WELL	API Number:	045-17426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298795	Type:	WELL	API Number:	045-17427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298796	Type:	WELL	API Number:	045-17428	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

<u>Producing Well</u>			
Comment:	Plunger lift		
Corrective Action:		Date:	
Facility ID: 298797 Type: WELL API Number: 045-17429 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger lift		
Corrective Action:		Date:	
Facility ID: 298798 Type: WELL API Number: 045-17430 Status: PR Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Plunger lift		
Corrective Action:		Date:	

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Gravel	Pass					
Rip Rap	Pass					
Sediment Traps	Pass					
Berms	Pass					
Ditches	Pass					
		Ditches	Pass			
		Gravel	Pass			
		Check Dams	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT