

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/29/2017

Submitted Date:

03/29/2017

Document Number:

673404372

FIELD INSPECTION FORM

Loc ID 313019 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 6720
Name of Operator: BAYLESS PRODUCER LLC* ROBERT L
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223370	WELL	PR	06/11/2014	GW	081-06734	BUCK PEAK 34-23 HD	WK

General Comment:

Inspected Facilities

Facility ID: 223370 Type: WELL API Number: 081-06734 Status: PR Insp. Status: WK

Workover

Comment: Inspector on location to witness MIT. (Form 42 notice document number 401234346).
5000 PSI chart and gauge for 300 PSI test.
MIT passed at 300 PSI for 15 minutes. Chart will be sent with Form 21.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Inspector on location to witness MIT. (Form 42 notice document number 401234346). 5000 PSI chart and gauge for 300 PSI test. MIT passed at 300 PSI for 15 minutes. Chart will be sent with Form 21.	waldrone	03/29/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401246831	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4111962