

Inspected FacilitiesFacility ID: 235972 Type: WELL API Number: 121-08462 Status: PA Insp. Status: PA**COGCC Comments**

Comment	User	Date
Tank battery equipment was removed per previous inspection (see attached photos).	ShermaSe	04/05/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673715187	Wescto Rudnick 32-27	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117011