

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2017

Submitted Date:

03/30/2017

Document Number:

666803071

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335505 _____ Murray, Richard _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|--------------------|------------------------|
| Ghan, Scott | | sghan@vnrlc.com | Sr. EH&S |
| Axelson, Aaron | 970-230-0926 | aaxelson@vnrlc.com | Sr. Production Foreman |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 279431 | WELL | PR | 03/01/2011 | GW | 045-11032 | JACKSON 44D-28-692 | PR |
| 279432 | WELL | PR | 03/01/2011 | GW | 045-11033 | JACKSON 33C-28-692 | SI |
| 279433 | WELL | PR | 03/01/2011 | GW | 045-11034 | JACKSON 43C-28-692 | PR |
| 280246 | WELL | PR | 02/18/2009 | GW | 045-11223 | JACKSON 34D-28-692 | PR |
| 298301 | WELL | PR | 01/20/2010 | GW | 045-17117 | JACKSON 44C-28-692 | PR |
| 298794 | WELL | PR | 01/13/2010 | GW | 045-17426 | JACKSON 43A-28-692 | PR |
| 298795 | WELL | PR | 01/11/2010 | GW | 045-17427 | JACKSON 33D-28-692 | PR |
| 298796 | WELL | PR | 11/11/2010 | GW | 045-17428 | JACKSON 33A-28-692 | PR |
| 298797 | WELL | PR | 01/13/2010 | GW | 045-17429 | JACKSON 34C-28-692 | PR |
| 298798 | WELL | PR | 01/13/2010 | GW | 045-17430 | JACKSON 44A-28-692 | PR |

General Comment:

| | | | | | |
|--------------------|----------|------------------|-----------------|----------|-------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|------------------------|--|-------|
| Yes/No | YES | | |
| Comment: | Bradenhead valves open | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | | |
|-----------------------|---|--|-----------|-------------|-----------|---------|-------|---------------|----|--|
| Facility ID: | 279431 | Type: | WELL | API Number: | 045-11032 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Facility ID: | 279432 | Type: | WELL | API Number: | 045-11033 | Status: | PR | Insp. Status: | SI | |
| Idle Well | | | | | | | | | | |
| Purpose: | <input checked="" type="checkbox"/> Shut In | <input type="checkbox"/> Temporarily Abandoned | Reminder: | | | | | | | |
| Comment: | last posted production numbers Jan 2016 | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Facility ID: | 279433 | Type: | WELL | API Number: | 045-11034 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Facility ID: | 280246 | Type: | WELL | API Number: | 045-11223 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Facility ID: | 298301 | Type: | WELL | API Number: | 045-17117 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Facility ID: | 298794 | Type: | WELL | API Number: | 045-17426 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Facility ID: | 298795 | Type: | WELL | API Number: | 045-17427 | Status: | PR | Insp. Status: | PR | |
| Producing Well | | | | | | | | | | |
| Comment: | Plunger lift | | | | | | | | | |
| Corrective Action: | | | | | | | Date: | | | |
| Facility ID: | 298796 | Type: | WELL | API Number: | 045-17428 | Status: | PR | Insp. Status: | PR | |

| Producing Well | | | |
|-----------------------|--------------|-------|--|
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |

Facility ID: 298797 Type: WELL API Number: 045-17429 Status: PR Insp. Status: PR

| Producing Well | | | |
|-----------------------|--------------|-------|--|
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |

Facility ID: 298798 Type: WELL API Number: 045-17430 Status: PR Insp. Status: PR

| Producing Well | | | |
|-----------------------|--------------|-------|--|
| Comment: | Plunger lift | | |
| Corrective Action: | | Date: | |

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | | | | | |
| Gravel | Pass | | | | | |
| | | Culverts | Pass | | | |
| Rip Rap | Pass | | | | | |
| Sediment Traps | Pass | | | | | |
| | | Ditches | Pass | | | |
| | | Gravel | Pass | | | |
| | | Check Dams | Pass | | | |
| Berms | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401247869 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4112991 |