

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2017

Submitted Date:

03/30/2017

Document Number:

675204075**FIELD INSPECTION FORM**Loc ID 323851 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES, INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|-----------------------------------|----------------------------------|------------------------------------|
| Engineering | | dnr_cogccengineering@state.co.us | All Engineering |
| Tahmahkera, Kerry | (970) 563-4000 | maralextech@gmail.com | All Inspections |
| Hartman, Robert | (970) 244-3041 | bhartman@blm.gov | Petroleum Engineer |
| O'Hare, Mickey | (970) 563-4000/ (719) 429-3529 | amohare@maralexinc.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 210985 | WELL | PR | 08/01/2012 | GW | 045-06743 | SOUTH SHALE RIDGE 10-7 | SI |

General Comment:

Pursuant to AOC NO. 1 V-609 well will be included in a "Compliance Schedule". Maralex will either: (1) plug and abandon the Noncompliant Wells in accordance with the Rules; or (2) conduct successful MITs on the Noncompliant Wells in accordance with the Rules.

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|------|--|
| Type | |
|------|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 210985 | Type: | WELL | API Number: | 045-06743 | Status: | PR | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____ | | | | | | | | | |
| Comment: <div>Last production on file was July 2014. No MIT on file.</div> | | | | | | | | | |
| Corrective Action: <div></div> Date: _____ | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401247467 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4112630 |
| 675204079 | SSR 10-7 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4112624 |