

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/05/2017

Submitted Date:

04/05/2017

Document Number:

674703808**FIELD INSPECTION FORM**
 Loc ID 335177 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2760	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211104	WELL	PR	04/07/1995	GW	045-06863	DOE 2-M-36	PR
260188	WELL	PR	06/05/2002	GW	045-07824	FEDERAL GM 31-36	PR
260201	WELL	PR	03/07/2002	GW	045-07829	FEDERAL GM 42-36	PR
260202	WELL	PR	06/05/2002	GW	045-07830	FEDERAL GM 41-36	PR
287810	WELL	PR	01/15/2008	GW	045-13074	FEDERAL GM 34-25	PR
287811	WELL	PR	11/13/2006	GW	045-13073	FEDERAL GM 441-36	PR
287812	WELL	PR	11/13/2006	GW	045-13072	FEDERAL GM 341-36	PR
287813	WELL	PR	11/13/2006	GW	045-13071	FEDERAL GM 432-36	PR
287815	WELL	PR	11/13/2006	GW	045-13070	FEDERAL GM 342-36	PR
287816	WELL	PR	11/13/2006	GW	045-13069	FEDERAL GM 431-36	PR
287818	WELL	PR	09/22/2007	GW	045-13067	FEDERAL GM 442-36	PR
287819	WELL	PR	11/13/2006	GW	045-13066	FEDERAL GM 541-36	PR
287820	WELL	PR	11/13/2006	GW	045-13065	FEDERAL GM 531-36	PR
287821	WELL	PR	11/13/2006	GW	045-13064	FEDERAL GM 344-25	PR
287822	WELL	PR	11/13/2006	GW	045-13063	FEDERAL GM 44-25	PR
287877	WELL	PR	11/14/2006	GW	045-13088	FEDERAL GM 331-36	PR

General Comment:

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical container at wells		
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
	Date:			

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	211104	Type:	WELL	API Number:	045-06863	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260188	Type:	WELL	API Number:	045-07824	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260201	Type:	WELL	API Number:	045-07829	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	260202	Type:	WELL	API Number:	045-07830	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287810	Type:	WELL	API Number:	045-13074	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287811	Type:	WELL	API Number:	045-13073	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287812	Type:	WELL	API Number:	045-13072	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287813	Type:	WELL	API Number:	045-13071	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			

Facility ID:	287815	Type:	WELL	API Number:	045-13070	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287816	Type:	WELL	API Number:	045-13069	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287818	Type:	WELL	API Number:	045-13067	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287819	Type:	WELL	API Number:	045-13066	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287820	Type:	WELL	API Number:	045-13065	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287821	Type:	WELL	API Number:	045-13064	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287822	Type:	WELL	API Number:	045-13063	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			
Facility ID:	287877	Type:	WELL	API Number:	045-13088	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well on plunger lift								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			
Ditches	Pass					
		Compaction	Pass			
Compaction	Pass					
Seeding	Pass					
Gravel	Pass					
		Ditches	Pass			
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703809	DOE 2-M-36 location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118195