

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/29/2017

Submitted Date:

03/31/2017

Document Number:

666803068**FIELD INSPECTION FORM**

Loc ID 335300 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelsson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264260	WELL	PR	07/27/2016	GW	045-08134	BRYNILDSON 14C - 20 - 692	PR
276111	WELL	PR	02/13/2012	GW	045-10428	BRYNILDSON 14B-20-692	PR
276112	WELL	PR	07/28/2009	GW	045-10427	BRYNILDSON 13A-20-692	PR
276113	WELL	PR	06/08/2009	GW	045-10426	BRYNILDSON 14D-20-692	PR
298340	WELL	PR	06/04/2009	GW	045-17144	BRYNILDSON 24C-20-692	PR
298341	WELL	PR	06/08/2009	GW	045-17145	BRYNILDSON 24B-20-692	PR
298342	WELL	PR	06/03/2009	GW	045-17146	BRYNILDSON 14A-20-692	PR
298343	WELL	PR	06/08/2009	GW	045-17147	BRYNILDSON 24A-20-692	PR
298344	WELL	PR	06/08/2009	GW	045-17148	BRYNILDSON 23A-20-692	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

9

Comment:

Corrective Action:

Date:

Type: Plunger Lift

9

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

3

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLS	STEEL AST		39.507067,-107.698424

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	264260	Type:	WELL	API Number:	045-08134	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276111	Type:	WELL	API Number:	045-10428	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276112	Type:	WELL	API Number:	045-10427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	276113	Type:	WELL	API Number:	045-10426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298340	Type:	WELL	API Number:	045-17144	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298341	Type:	WELL	API Number:	045-17145	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298342	Type:	WELL	API Number:	045-17146	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298343	Type:	WELL	API Number:	045-17147	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID: 298344 Type: WELL API Number: 045-17148 Status: PR Insp. Status: PR

Producing Well

Comment: [Plunger lift](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Seeding	Pass					
Ditches	Pass					
		Culverts	Pass			
Compaction	Pass					
		Gravel	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248082	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113257