

Inspection Photos

04/06/2017

Operator: Bill Barrett Corp #10071

Location ID: 427467

Inspection Doc. Number: 682501847

Weld County, CO

NWNW Section 18 T5N R51W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: BBC
Location ID: 427467



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: BBC
Location ID: 427467



Photo 2: Photo taken from the location, facing north.
Photo shows vegetation over the reclamation area.



Photo 3: Photo taken from the location, facing east.
Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: BBC
Location ID: 427467



Photo 4: Photo taken from the location, facing south.
Photo shows vegetation over the reclamation area.



Photo 5: Photo taken from the location, facing west.
Photo shows vegetation over the reclamation area