

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/31/2017

Submitted Date:

03/31/2017

Document Number:

672500481**FIELD INSPECTION FORM**
 Loc ID 305447 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 370 17TH STREET #2170City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG
434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG
436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG
436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG
436739	WELL	DG	10/30/2016	LO	123-39246	Woolley Sosa 2G-7H-E168	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

#

Comment:

APPROX 32' SOUND WALLS AROUND LOCATION FOR SOUND MITIGATION

Corrective Action:

Date:

Type: Ancillary equipment

#

Comment:

APPROX 20' MOBILE SOUND WALLS INSIDE LOCATION FOR SOUND MITIGATION

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Field Flare

Comment:

NOT IN USE AT TIM OF INSPECTION

Corrective Action:

Date:

Inspected Facilities

Facility ID: 434333 Type: WELL API Number: 123-38104 Status: DG Insp. Status: DG

Complaint

Comment: [Complaint #: 200441258](#)

[Field Inspector Assigned: Jason E. Gomez](#)

[Complaint Received:](#)

[Date: 3-31-2017 Time 0900 Hrs](#)

[Contacted by Inspector:](#)

[Date: Time Hrs](#)

[Well Number#: Location #: 305447](#)

[Inspection Document #: 672500481](#)

[Complainant: Gary Gianetti Phone: 860-933-0524](#)

[Address: 1379 Padfield Pl, Erie CO 80516](#)

[Nature of complaint: Noise](#)

[Field Inspector Actions:](#)

[On 3-31-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a noise complaint at the residence of the complainant Gary Gianetti 1379 Padfield PL in Erie Colorado.](#)

[I performed a complete site inspection of the location on 3-31-2017. At the time of inspection, I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information.](#)

[All information reviewed and site inspection information were submitted to the complaint specialist for further review.](#)

[No violations of COGCC rules were observed at the time of the inspection.](#)

Corrective Action:

Date:

Facility ID: 434334 Type: WELL API Number: 123-38105 Status: DG Insp. Status: DG

Facility ID: 434335 Type: WELL API Number: 123-38106 Status: DG Insp. Status: DG

Complaint

Comment:

Complaint #: 200441261

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 3-31-2017 Time 0900 Hrs

Contacted by Inspector:

Date: 3-31-2017 Time 0930 Hrs

Well Number#: Location #: 305447

Inspection Document #: 672500481

Complainant: Sally Towner Phone: 303-828-4834

Address: 1369 Washburn St, Erie CO 80516

Nature of complaint: Noise

Field Inspector Actions:

On 3-31-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a noise complaint at the residence of the complainant Sally Towner 1369 Washburn St in Erie Colorado.

I performed a complete site inspection of the location on 3-31-2017. At the time of inspection, I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Facility ID: 434336	Type: WELL	API Number: 123-38107	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 434337	Type: WELL	API Number: 123-38108	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 434338	Type: WELL	API Number: 123-38109	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 434339	Type: WELL	API Number: 123-38110	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 434340	Type: WELL	API Number: 123-38111	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 434341	Type: WELL	API Number: 123-38112	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID: 434342	Type: WELL	API Number: 123-38113	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

Facility ID:	434343	Type:	WELL	API Number:	123-38114	Status:	DG	Insp. Status:	DG
Facility ID:	436731	Type:	WELL	API Number:	123-39241	Status:	DG	Insp. Status:	DG
Facility ID:	436733	Type:	WELL	API Number:	123-39242	Status:	DG	Insp. Status:	DG
Facility ID:	436738	Type:	WELL	API Number:	123-39245	Status:	DG	Insp. Status:	DG
Facility ID:	436739	Type:	WELL	API Number:	123-39246	Status:	DG	Insp. Status:	DG

Rig:	Rig Name: <u>ENSIGN 140</u>	Pusher/Rig Manager: <u>ROBERT</u>
	Permit Posted: Yes	Access Sign: Yes

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: _____
Drill Fluids YES

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: YES Disposal Location: WASTE CONNECTION

Comment:

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment: NOT IN USE AT TIME OF INSPECTION

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass					
Rip Rap	Pass			Vehicle Tracking	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401251437	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116396