

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2017

Submitted Date:

04/03/2017

Document Number:

672500482

FIELD INSPECTION FORM

Loc ID 444349 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Mattox, Jennifer	303-692-3144	jennifer.mattox@state.co.us	environmental protection specialist
Adamczyk, Megan		megan.adamczyk@state.co.us	
Precup, Jim		james.precup@state.co.us	
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444346	WELL	DG	12/28/2016	LO	123-42571	GARFIELD 28N-14HZ	DG
444347	WELL	DG	12/27/2016	LO	123-42572	GARFIELD 36N-35HZ	DG
444348	WELL	DG	12/30/2016	LO	123-42573	GARFIELD 15C-35HZ	DG
444351	WELL	DG	01/02/2017	LO	123-42575	GARFIELD 37N-35HZ	DG
444352	WELL	DG	12/31/2016	LO	123-42576	GARFIELD 15N-35HZ	DG
444355	WELL	DG	12/29/2016	LO	123-42579	GARFIELD 2N-14HZ	DG
444357	WELL	DG	01/01/2017	LO	123-42581	GARFIELD 27C-14HZ	DG

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment	#		corrective date
Comment:	APPROX 32' SOUND WALLS USED ON WEST AND SOUTH END OF LOCATION		
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	BALES USED FOR SOUND MITIGATION ON NORTH AND EAST SIDE OF LOCATION		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Field Flare		
Comment:	NOT IN USE AT TIME OF INSPECTION		
Corrective Action:			Date:

Inspected Facilities

Facility ID: 444346 Type: WELL API Number: 123-42571 Status: DG Insp. Status: DG

Complaint

Comment:

Complaint #: 200441271
 Field Inspector Assigned: Jason E. Gomez
 Complaint Received:
 Date: 4-3-2017 Time 1300 Hrs
 Contacted by Inspector:
 Date: 4-3-2017 Time 1530 Hrs
 Well Number#: Location #: 444349
 Inspection Document #: 672500482
 Complainant: Brad Oconnel Phone: 303-908-8138
 Address: 10463 WCR 6, Fort Lupton, CO 80621
 Nature of complaint: Noise/Odors
 Field Inspector Actions:
 On 4-3-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a complaint at the residence of the complainant Brad Oconnel 10463 WCR 6 Fort Lupton Colorado.
 I contacted the complainant he indicated the noise was coming from the drilling rig located to the east of his home, he said there was a loud air horn being used at the location at all times which was disturbing. He also said he was smelling strong diesel odors coming from the drilling rig as well.
 I performed a complete site inspection of the location on 4-3-2017. At the time of inspection, as I approached the location off of WCR 6 I detected odors which appeared to be coming from the rig. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaint. All lighting on the rig were pointed down and toward the center of the location at the time of the inspection.
 I spoke with the Kerr Mcgee company man at the location he indicated the horn used was a safety horn, which he would make, sure was only tested twice a day during reasonable daylight hours. He also said they would check the masking agent used to mitigate the drill cuttings odors and attempt to adjust them to reduce the odors coming from the rig.
 Due to the odors smelled of location this complaint was forwarded to the CDPHE for further review.
 All information reviewed and site inspection information were submitted to the complaint specialist for further review.
 No other violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: EXTREME RIG 24 Pusher/Rig Manager: JOHN TRUETT
 Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES

Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: YES Disposal Location: WASTE MANAGEMENT

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 444347 Type: WELL API Number: 123-42572 Status: DG Insp. Status: DG

Facility ID: 444348 Type: WELL API Number: 123-42573 Status: DG Insp. Status: DG

Facility ID: 444351 Type: WELL API Number: 123-42575 Status: DG Insp. Status: DG

Facility ID: 444352 Type: WELL API Number: 123-42576 Status: DG Insp. Status: DG

Facility ID: 444355 Type: WELL API Number: 123-42579 Status: DG Insp. Status: DG

Facility ID: 444357 Type: WELL API Number: 123-42581 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Ditches	Pass			Vehicle Tracking	Pass	
Sediment Traps	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401251438	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116397