

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/03/2017

Submitted Date:

04/03/2017

Document Number:

672500483

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
449174 _____ Gomez, Jason _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
 Address: 1801 BROADWAY #500
 City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogccinspections@gwogco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449164	WELL	XX	02/09/2017		001-09993	Ocho LD 17-367HC	DG
449165	WELL	XX	02/09/2017		001-09994	Ocho LD 17-367HN	DG
449167	WELL	XX	02/09/2017		001-09996	Ocho LD 17-364HC	DG
449172	WELL	XX	02/09/2017		001-10001	Ocho LD 17-365HN	DG

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment

#

corrective date

Comment: APPROX 28' SOUND WALLS ON NORTH, EAST AND WEST SIDE OF LOCATION
BERMS ON SOUTH AND WEST ENDS

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type Field Flare

Comment: NOT IN USE AT TIME OF INSPECTION

Corrective Action:

Date:

Inspected Facilities

Facility ID: 449164 Type: WELL API Number: 001-09993 Status: XX Insp. Status: DG

Complaint

Comment: **Complaint #:** 200441264 / 200441265 / 200441266
Field Inspector Assigned: Jason E. Gomez
Complaint Received:
Date: 3-31-2017 Time 1000 Hrs
Contacted by Inspector:
Date: 4-3-2017 Time 1530 Hrs
Well Number#: Location #: 449174
Inspection Document #: 672500483
Complainant: Lisa Cloutier / Verra Clark / Laurie Jorgensen **Phone:** 720-271-0946 / 720-261-1844 / 303-835-2918
Address: 6124 E 162nd Ave / 16123 Krameria ct, 6103 E 161st Ave, Brighton CO 80602
Nature of complaint: Noise/Lights/Odors
Field Inspector Actions:
 On 4-3-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a complaint at the residence of the complainants Lisa Cloutier 6124 E 162nd Ave, Verra Clark 16123 Krameria Ct, and Laurie Jorgensen 6103 E 161st Ave, Brighton Colorado.
 I attempted to make phone contact with the complainants but I did not receive any call back from any of the complainants.
 I performed a complete site inspection of the location on 4-3-2017. At the time of inspection, I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. All lighting on the rig were pointed down and toward the center of the location at the time of the inspection see inspections Doc#672500483 for attached photos of rig lighting. No odors were detected off the location at the time of the inspection.
 All information reviewed and site inspection information were submitted to the complaint specialist for further review.
 No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: PRECISION RIG 460 Pusher/Rig Manager: Marvin Hacworth
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____

Multi-Well: YES Disposal Location: WASTE MANAGEMENT

Comment:

Corrective Action:

Date:

Facility ID: 449165 Type: WELL API Number: 001-09994 Status: XX Insp. Status: DG

Facility ID: 449167 Type: WELL API Number: 001-09996 Status: XX Insp. Status: DG

Facility ID: 449172 Type: WELL API Number: 001-10001 Status: XX Insp. Status: DG

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Silt Fences	Pass					
Berms	Pass					
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Mulching	Pass					
Ditches	Pass			Vehicle Tracking	Pass	
Slope Roughening	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401251439	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116398
672500485	GW Ambient sound study	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116393