

Inspection Photos
Location Name: Iles Dome Unit 25
API: 05-081-05086



Photo 1. View at entrance to location facing south.

Inspection Photos
Location Name: Iles Dome Unit 25
API: 05-081-05086



Photo 2. Uncovered trash can at wellhead.



Photo 3. Cellar full of oily liquid without 2 feet of freeboard.