

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2017

Submitted Date:

04/11/2017

Document Number:

666803098**FIELD INSPECTION FORM**

Loc ID 335488 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298067	WELL	PR	01/31/2010	GW	045-17050	SAVAGE RWF 544-26	PR
298068	WELL	PR	02/26/2009	GW	045-17052	SAVAGE RWF 543-26	PR
298069	WELL	PR	12/31/2009	GW	045-17053	SAVAGE RWF 343-26	PR
298070	WELL	PR	12/31/2009	GW	045-17054	SAVAGE RWF 43-26	PR
298071	WELL	PR	01/31/2010	GW	045-17055	SAVAGE RWF 434-26	PR
298072	WELL	PR	01/31/2010	GW	045-17056	SAVAGE RWF 34-26	PR
298073	WELL	PR	01/31/2010	GW	045-17057	SAVAGE RWF 533-26	PR
298074	WELL	PR	12/31/2009	GW	045-17058	SAVAGE RMV 47-26	PR
298075	WELL	PR	01/11/2010	GW	045-17059	SAVAGE RWF 433-26	PR
298076	WELL	PR	01/31/2010	GW	045-17060	SAVAGE RWF 344-26	PR
298077	WELL	PR	04/16/2011	GW	045-17061	SAVAGE RWF 44-26	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

11

Comment:

Corrective Action:

Date:

Type: Plunger Lift

11

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

2

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST		39.491577,-107.849618
Comment:					
Corrective Action:					
Date:					

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No NO

Comment:

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	298067	Type:	WELL	API Number: 045-17050	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298068	Type:	WELL	API Number: 045-17052	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298069	Type:	WELL	API Number: 045-17053	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298070	Type:	WELL	API Number: 045-17054	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298071	Type:	WELL	API Number: 045-17055	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298072	Type:	WELL	API Number: 045-17056	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298073	Type:	WELL	API Number: 045-17057	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298074	Type:	WELL	API Number: 045-17058	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:

Facility ID:	298075	Type:	WELL	API Number:	045-17059	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	298076	Type:	WELL	API Number:	045-17060	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	298077	Type:	WELL	API Number:	045-17061	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
		Gravel	Pass			
Seeding	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT