

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2017

Submitted Date:

04/06/2017

Document Number:

674103991**FIELD INSPECTION FORM**

Loc ID 418100	Inspector Name: Rickard, Jeff	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 14 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																							
<b>Operator Information:</b> OGCC Operator Number: <u>47120</u> Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u> Address: <u>P O BOX 173779</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>																																																																											
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, General</td> <td></td> <td>COGCCinspections@Anadarko.com</td> <td></td> </tr> </table>					Contact Name	Phone	Email	Comment	, General		COGCCinspections@Anadarko.com																																																																
Contact Name	Phone	Email	Comment																																																																								
, General		COGCCinspections@Anadarko.com																																																																									
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>418105</td> <td>WELL</td> <td>TA</td> <td>01/01/2017</td> <td>OW</td> <td>069-06417</td> <td>ENCORE 5-12</td> <td>SI</td> </tr> <tr> <td>418107</td> <td>WELL</td> <td>TA</td> <td>01/01/2017</td> <td>OW</td> <td>069-06419</td> <td>ENCORE 21-12</td> <td>SI</td> </tr> <tr> <td>418108</td> <td>WELL</td> <td>PR</td> <td>08/27/2013</td> <td>OW</td> <td>069-06420</td> <td>ENCORE 4-12</td> <td>PR</td> </tr> <tr> <td>418109</td> <td>WELL</td> <td>TA</td> <td>11/08/2016</td> <td>OW</td> <td>069-06421</td> <td>ENCORE 6-12</td> <td>PR</td> </tr> <tr> <td>418112</td> <td>WELL</td> <td>PR</td> <td>07/01/2016</td> <td>OW</td> <td>069-06423</td> <td>ENCORE 18-12</td> <td>PR</td> </tr> <tr> <td>418192</td> <td>WELL</td> <td>SI</td> <td>01/01/2017</td> <td>OW</td> <td>069-06424</td> <td>ENCORE 2-12</td> <td>PR</td> </tr> <tr> <td>418195</td> <td>WELL</td> <td>SI</td> <td>01/01/2017</td> <td>OW</td> <td>069-06425</td> <td>ENCORE 3-12</td> <td>PR</td> </tr> <tr> <td>442176</td> <td>TANK BATTERY</td> <td>AC</td> <td>06/24/2015</td> <td></td> <td>-</td> <td>ENCORE TANK BATTERY 41N-12HZ</td> <td>AC</td> </tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	418105	WELL	TA	01/01/2017	OW	069-06417	ENCORE 5-12	SI	418107	WELL	TA	01/01/2017	OW	069-06419	ENCORE 21-12	SI	418108	WELL	PR	08/27/2013	OW	069-06420	ENCORE 4-12	PR	418109	WELL	TA	11/08/2016	OW	069-06421	ENCORE 6-12	PR	418112	WELL	PR	07/01/2016	OW	069-06423	ENCORE 18-12	PR	418192	WELL	SI	01/01/2017	OW	069-06424	ENCORE 2-12	PR	418195	WELL	SI	01/01/2017	OW	069-06425	ENCORE 3-12	PR	442176	TANK BATTERY	AC	06/24/2015		-	ENCORE TANK BATTERY 41N-12HZ	AC
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																				
418105	WELL	TA	01/01/2017	OW	069-06417	ENCORE 5-12	SI																																																																				
418107	WELL	TA	01/01/2017	OW	069-06419	ENCORE 21-12	SI																																																																				
418108	WELL	PR	08/27/2013	OW	069-06420	ENCORE 4-12	PR																																																																				
418109	WELL	TA	11/08/2016	OW	069-06421	ENCORE 6-12	PR																																																																				
418112	WELL	PR	07/01/2016	OW	069-06423	ENCORE 18-12	PR																																																																				
418192	WELL	SI	01/01/2017	OW	069-06424	ENCORE 2-12	PR																																																																				
418195	WELL	SI	01/01/2017	OW	069-06425	ENCORE 3-12	PR																																																																				
442176	TANK BATTERY	AC	06/24/2015		-	ENCORE TANK BATTERY 41N-12HZ	AC																																																																				

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

# 5

Comment: Corrective Action: Date: 

Type: Compressor

# 1

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 1

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 7

Comment: Corrective Action: Date: 

Type: Horizontal Heated Separator

# 7

Comment: Corrective Action: Date: 

Type: VRT

# 3

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLS	PBV FIBERGLASS		,
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

**Paint**Condition: Other (Content) Other (Capacity)

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	11	300 BBLs	STEEL AST		40.419910,-104.955030	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No						
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 418105 Type: WELL API Number: 069-06417 Status: TA Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: HZ prep

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418107 Type: WELL API Number: 069-06419 Status: TA Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: HZ prep

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418108 Type: WELL API Number: 069-06420 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418109 Type: WELL API Number: 069-06421 Status: TA Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418112 Type: WELL API Number: 069-06423 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

<b><u>BradenHead</u></b>	
Comment:	<input type="text" value="Braden head is exposed at surface."/>
Corrective Action:	<input type="text"/> Date: <input type="text"/>

Facility ID:	<u>418192</u>	Type:	<u>WELL</u>	API Number:	<u>069-06424</u>	Status:	<u>SI</u>	Insp. Status:	<u>PR</u>
--------------	---------------	-------	-------------	-------------	------------------	---------	-----------	---------------	-----------

<b><u>Producing Well</u></b>	
Comment:	<input type="text" value="PR"/>
Corrective Action:	<input type="text"/> Date: <input type="text"/>

<b><u>BradenHead</u></b>	
Comment:	<input type="text" value="Braden head is exposed at surface."/>
Corrective Action:	<input type="text"/> Date: <input type="text"/>

Facility ID:	<u>418195</u>	Type:	<u>WELL</u>	API Number:	<u>069-06425</u>	Status:	<u>SI</u>	Insp. Status:	<u>PR</u>
--------------	---------------	-------	-------------	-------------	------------------	---------	-----------	---------------	-----------

<b><u>Producing Well</u></b>	
Comment:	<input type="text" value="PR"/>
Corrective Action:	<input type="text"/> Date: <input type="text"/>

<b><u>BradenHead</u></b>	
Comment:	<input type="text" value="Braden head is exposed at surface."/>
Corrective Action:	<input type="text"/> Date: <input type="text"/>

Facility ID:	<u>442176</u>	Type:	<u>TANK</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
--------------	---------------	-------	-------------	-------------	----------	---------	-----------	---------------	-----------

<b><u>Producing Well</u></b>	
Comment:	<input type="text" value="PR"/>
Corrective Action:	<input type="text"/> Date: <input type="text"/>

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? PassProduction areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? \_\_\_\_\_

Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐Multi-Well Location ☐



**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401252770	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117612">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117612</a>
674103992	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117595">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117595</a>