

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2017

Submitted Date:

04/04/2017

Document Number:

674703805**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 335667      LONGWORTH, MIKE      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER      State: CO      Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	<a href="#">EnCana Inspection email</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282296	WELL	PR	08/03/2006	GW	045-11726	N PARACHUTE WF06C-23 F23596	PR
291476	WELL	PR	01/31/2009	GW	045-14383	N PARACHUTE WF12D-23 F23596	PR
291501	WELL	PR	07/31/2008	GW	045-14427	N PARACHUTE WF14C-23 F23596	PR
291502	WELL	PR	07/23/2007	GW	045-14426	N PARACHUTE WF15A-23 F23596	PR
291503	WELL	PR	01/31/2009	GW	045-14425	N PARACHUTE WF05C-23 F23596	PR
291505	WELL	PR	02/01/2012	GW	045-14423	N PARACHUTE WF11D-23 F23596	PR
291506	WELL	PR	07/08/2009	GW	045-14422	N PARACHUTE WF06D-23 F23596	PR
291508	WELL	PR	04/11/2012	GW	045-14421	N. PARACHUTE WF 14A-23F23596	PR
291512	WELL	PR	03/01/2009	GW	045-14419	N PARACHUTE WF12A-23 F23596	PR
291514	WELL	PR	07/23/2007	GW	045-14418	N PARACHUTE WF14B-23 F23596	PR
291518	WELL	PR	04/01/2008	GW	045-14417	N PARACHUTE WF05D-23 F23596	PR
291525	WELL	PR	01/01/2009	GW	045-14414	N PARACHUTE WF11B-23 F23596	PR
291527	WELL	PR	07/23/2007	GW	045-14412	N PARACHUTE WF11A-23 F23596	PR
291529	WELL	PR	01/19/2009	GW	045-14410	N PARACHUTE WF12B-23 F23596	PR
291530	WELL	PR	04/01/2012	GW	045-14408	N PARACHUTE WF11C-23 F23596	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date:

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 15		
Comment:	Gas lift		
Corrective Action:		Date:	

Type: Bird Protectors	# 11	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 20	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 15	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical container at tank battery	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	282296	Type:	WELL	API Number: 045-11726	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
Facility ID:	291476	Type:	WELL	API Number: 045-14383	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
Facility ID:	291501	Type:	WELL	API Number: 045-14427	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
Facility ID:	291502	Type:	WELL	API Number: 045-14426	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
Facility ID:	291503	Type:	WELL	API Number: 045-14425	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
Facility ID:	291505	Type:	WELL	API Number: 045-14423	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
Facility ID:	291506	Type:	WELL	API Number: 045-14422	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:
Facility ID:	291508	Type:	WELL	API Number: 045-14421	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing well on plunger lift					
Corrective Action:						Date:

Facility ID: 291512	Type: WELL	API Number: 045-14419	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 291514	Type: WELL	API Number: 045-14418	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 291518	Type: WELL	API Number: 045-14417	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 291525	Type: WELL	API Number: 045-14414	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 291527	Type: WELL	API Number: 045-14412	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 291529	Type: WELL	API Number: 045-14410	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

Facility ID: 291530	Type: WELL	API Number: 045-14408	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well on plunger lift

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
Hydro Mulch	Pass					
Compaction	Pass					
		Gravel	Pass			
Ditches	Pass					
		Culverts	Pass			
Check Dams	Pass					
				Material Handling And Spill Prevention	Pass	
		Compaction	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401253219	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118210</a>