

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401256449

Date Received:

04/13/2017

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

450008

## SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u>	Operator No: <u>47120</u>	<b>Phone Numbers</b>
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>( )</u>
Contact Person: <u>Paul Schwarz</u>		Email: <u>Paul.Schwarz@Anadarko.com</u>

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401256449

Initial Report Date: 04/11/2017 Date of Discovery: 04/10/2017 Spill Type: Recent Spill

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NENW SEC 25 TWP 2N RNG 66W MERIDIAN 6

Latitude: 40.116298 Longitude: -104.727580

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

#### Reference Location:

Facility Type: TANK BATTERY ☐ Facility/Location ID No \_\_\_\_\_  
☒ No Existing Facility or Location ID No.  
☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=5 and <100

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: OTHER Other(Specify): Tank Battery Facility

Weather Condition: Sunny, 50°F

Surface Owner: FEE Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

*As defined in COGCC 100-Series Rules*

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On April 10, 2017, a produced water tank overflowed due to an automation failure at the Shafer 21-25, Bidding USX W25-06 tank battery. Approximately 6 barrels of oil and 1 barrel of produced water released inside secondary containment. A vacuum truck was deployed to recover the puddled fluids inside the containment. The analytical results and excavation details will be summarized in a supplemental report. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
4/11/2017	Weld County	Roy Rudisill	-	Notified via Email
4/11/2017	Weld County	Tom Parko	-	Notified via Email
4/11/2017	Weld County	Troy Swain	-	Notified via Email
4/11/2017	Landowner	Landowner	-	Notified via Phone

**OPERATOR COMMENTS:**

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Paul Schwarz

Title: HSE Representative Date: 04/13/2017 Email: Paul.Schwarz@Anadarko.com

**COA Type**

**Description**

	Provide documentation justifying closure request within 90 days of release via supplemental form 19. If investigation and remediation require further actions beyond 90 days then submit form 27 for approval within 90 days of spill (9July2017).
--	--

**Attachment Check List**

<u>Att Doc Num</u>	<u>Name</u>
401256449	SPILL/RELEASE REPORT(INITIAL)
401256453	OTHER
401257107	TOPOGRAPHIC MAP
401258875	FORM 19 SUBMITTED

Total Attach: 4 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	pushed back to draft at request of operator to correct a data entry error	04/13/2017

Total: 1 comment(s)