

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2017

Submitted Date:

04/07/2017

Document Number:

674004995**FIELD INSPECTION FORM**

Loc ID 336220	Inspector Name: Carlile, Craig	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 17 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																							
<b>Operator Information:</b> OGCC Operator Number: <u>47120</u> Name of Operator: <u>KERR MCGEE OIL &amp; GAS ONSHORE LP</u> Address: <u>P O BOX 173779</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>																																																																											
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, Inspections</td> <td></td> <td>COGCCinspections@Anadarko.com</td> <td><a href="#">All Inspections</a></td> </tr> </table>					Contact Name	Phone	Email	Comment	, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>																																																															
Contact Name	Phone	Email	Comment																																																																								
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>																																																																								
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>251524</td> <td>WELL</td> <td>TA</td> <td>08/09/2016</td> <td>GW</td> <td>123-19327</td> <td>STATE OF COLROADO BB UNIT 1</td> <td>TA</td> </tr> <tr> <td>275424</td> <td>WELL</td> <td>PR</td> <td>02/06/2007</td> <td>GW</td> <td>123-22636</td> <td>HAMLIN STATE 6-36</td> <td>SI</td> </tr> <tr> <td>416089</td> <td>WELL</td> <td>PR</td> <td>12/12/2011</td> <td>OW</td> <td>123-31257</td> <td>CARMA 3-36</td> <td>PR</td> </tr> <tr> <td>416117</td> <td>WELL</td> <td>PR</td> <td>11/11/2011</td> <td>GW</td> <td>123-31282</td> <td>CARMA 5-36</td> <td>PR</td> </tr> <tr> <td>416124</td> <td>WELL</td> <td>PR</td> <td>12/12/2011</td> <td>GW</td> <td>123-31287</td> <td>CARMA 12-36</td> <td>SI</td> </tr> <tr> <td>417663</td> <td>WELL</td> <td>PR</td> <td>12/12/2011</td> <td>OW</td> <td>123-31710</td> <td>CARMA 21-36</td> <td>PR</td> </tr> <tr> <td>417669</td> <td>WELL</td> <td>PR</td> <td>12/13/2011</td> <td>OW</td> <td>123-31714</td> <td>CARMA 32-36</td> <td>SI</td> </tr> <tr> <td>417671</td> <td>WELL</td> <td>PR</td> <td>12/12/2011</td> <td>GW</td> <td>123-31716</td> <td>CARMA 22-36</td> <td>PR</td> </tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	251524	WELL	TA	08/09/2016	GW	123-19327	STATE OF COLROADO BB UNIT 1	TA	275424	WELL	PR	02/06/2007	GW	123-22636	HAMLIN STATE 6-36	SI	416089	WELL	PR	12/12/2011	OW	123-31257	CARMA 3-36	PR	416117	WELL	PR	11/11/2011	GW	123-31282	CARMA 5-36	PR	416124	WELL	PR	12/12/2011	GW	123-31287	CARMA 12-36	SI	417663	WELL	PR	12/12/2011	OW	123-31710	CARMA 21-36	PR	417669	WELL	PR	12/13/2011	OW	123-31714	CARMA 32-36	SI	417671	WELL	PR	12/12/2011	GW	123-31716	CARMA 22-36	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																				
251524	WELL	TA	08/09/2016	GW	123-19327	STATE OF COLROADO BB UNIT 1	TA																																																																				
275424	WELL	PR	02/06/2007	GW	123-22636	HAMLIN STATE 6-36	SI																																																																				
416089	WELL	PR	12/12/2011	OW	123-31257	CARMA 3-36	PR																																																																				
416117	WELL	PR	11/11/2011	GW	123-31282	CARMA 5-36	PR																																																																				
416124	WELL	PR	12/12/2011	GW	123-31287	CARMA 12-36	SI																																																																				
417663	WELL	PR	12/12/2011	OW	123-31710	CARMA 21-36	PR																																																																				
417669	WELL	PR	12/13/2011	OW	123-31714	CARMA 32-36	SI																																																																				
417671	WELL	PR	12/12/2011	GW	123-31716	CARMA 22-36	PR																																																																				

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251524	WELL	TA	08/09/2016	GW	123-19327	STATE OF COLROADO BB UNIT 1	TA
275424	WELL	PR	02/06/2007	GW	123-22636	HAMLIN STATE 6-36	SI
416089	WELL	PR	12/12/2011	OW	123-31257	CARMA 3-36	PR
416117	WELL	PR	11/11/2011	GW	123-31282	CARMA 5-36	PR
416124	WELL	PR	12/12/2011	GW	123-31287	CARMA 12-36	SI
417663	WELL	PR	12/12/2011	OW	123-31710	CARMA 21-36	PR
417669	WELL	PR	12/13/2011	OW	123-31714	CARMA 32-36	SI
417671	WELL	PR	12/12/2011	GW	123-31716	CARMA 22-36	PR

<b>General Comment:</b>
-------------------------

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	210 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with crude oil tank.			
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	OTHER	STEEL AST		40.184860,-104.955500
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	315 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 251524 Type: WELL API Number: 123-19327 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Signage, Horizontal Prep

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 275424 Type: WELL API Number: 123-22636 Status: PR Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 416089 Type: WELL API Number: 123-31257 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 416117 Type: WELL API Number: 123-31282 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 416124 Type: WELL API Number: 123-31287 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: [Bradenhead plumbed to surface.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 417663 Type: WELL API Number: 123-31710 Status: PR Insp. Status: PR**Producing Well**Comment: [PR](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: [Bradenhead plumbed to surface.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 417669 Type: WELL API Number: 123-31714 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: [Bradenhead plumbed to surface.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 417671 Type: WELL API Number: 123-31716 Status: PR Insp. Status: PR**Producing Well**Comment: [PR](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**Comment: [Bradenhead plumbed to surface.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐



**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection.</a>	carlilec	04/07/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401253702	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118817">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118817</a>
674004996	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118812">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118812</a>