

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2017

Submitted Date:

04/07/2017

Document Number:

674004997

FIELD INSPECTION FORM

Loc ID 336070 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

19 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|-------------------------------|---------------------------------|
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 240567 | WELL | PR | 06/30/2010 | OW | 123-08355 | CONRAD HOPP JR. GAS UNIT 1 | PR |
| 251478 | WELL | PR | 01/21/1997 | GW | 123-19281 | HOPP CONRAD JR. GAS UNIT 2 | PR |
| 289861 | WELL | PR | 10/15/2008 | GW | 123-24944 | CARMA 1-35 | PR |
| 289862 | WELL | PR | 10/28/2008 | GW | 123-24943 | CARMA 2-35 | PR |
| 289863 | WELL | PR | 02/21/2014 | OW | 123-24942 | CARMA 8-35 | PR |
| 289864 | WELL | PR | 03/13/2014 | GW | 123-24941 | CARMA 7-35 | PR |
| 292735 | WELL | PR | 03/12/2014 | OW | 123-26376 | CARMA 24-35 | PR |
| 292736 | WELL | TA | 08/09/2016 | OW | 123-26375 | CARMA 41-35 | TA |
| 292760 | WELL | TA | 08/09/2016 | OW | 123-26377 | CARMA 21-35 | TA |

General Comment:

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|-------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Chainlink | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Chainlink | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Chainlink | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-----------------------------------|-----|-------|-----------------|
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 2 | | |

| | | | |
|---------------------|-----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 6 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|---------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 210 Bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 6 | OTHER | STEEL AST | | 40.185990,-104.966280 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 315 Bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | |
|--------------------|-----|-------|--|
| Venting: | | | |
| Yes/No | YES | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-------------------|-------|--|
| Flaring: | | | |
| Type | Ignitor/Combustor | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | |
|---|--------------------------|------------------------------|---|
| Facility ID: <u>240567</u> | Type: <u>WELL</u> | API Number: <u>123-08355</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: <u>PR</u> | Corrective Action: _____ | | Date: _____ |
| BradenHead | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | Corrective Action: _____ | | Date: _____ |
| Facility ID: <u>251478</u> | Type: <u>WELL</u> | API Number: <u>123-19281</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Idle Well | | | |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned | Reminder: _____ | | |
| Comment: _____ | Corrective Action: _____ | | Date: _____ |
| BradenHead | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | Corrective Action: _____ | | Date: _____ |
| Facility ID: <u>289861</u> | Type: <u>WELL</u> | API Number: <u>123-24944</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Idle Well | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned | Reminder: _____ | | |
| Comment: _____ | Corrective Action: _____ | | Date: _____ |
| BradenHead | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | Corrective Action: _____ | | Date: _____ |
| Facility ID: <u>289862</u> | Type: <u>WELL</u> | API Number: <u>123-24943</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: <u>PR</u> | Corrective Action: _____ | | Date: _____ |
| BradenHead | | | |
| Comment: <u>Bradenhead plumbed to surface.</u> | Corrective Action: _____ | | Date: _____ |
| Facility ID: <u>289863</u> | Type: <u>WELL</u> | API Number: <u>123-24942</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: <u>PR</u> | Corrective Action: _____ | | Date: _____ |

BradenHead

Comment:

Corrective Action:

Date:

Facility ID: 289864 Type: WELL API Number: 123-24941 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Comment:

Corrective Action:

Date:

Facility ID: 292735 Type: WELL API Number: 123-26376 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Comment:

Corrective Action:

Date:

Facility ID: 292736 Type: WELL API Number: 123-26375 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

Comment:

Corrective Action:

Date:

BradenHead

Comment:

Corrective Action:

Date:

Facility ID: 292760 Type: WELL API Number: 123-26377 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder:

Comment:

Corrective Action:

Date:

BradenHead

Comment:

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

COGCC Comments

| Comment | User | Date |
|-------------------------------------|----------|------------|
| Routine inspection. | carlilec | 04/07/2017 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401253703 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118818 |
| 674004998 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4118813 |