

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2017

Submitted Date:

04/10/2017

Document Number:

674703812**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 324080 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2760 | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 256385 | WELL | PR | 11/19/1999 | GW | 045-07448 | UNOCAL GM 44-1 | PR |
| 429917 | WELL | PR | 03/15/2013 | GW | 045-21682 | WPX Energy GM 441-12 | PR |
| 430274 | WELL | PR | 03/15/2013 | GW | 045-21712 | WPX Energy GM 341-12 | PR |
| 430275 | WELL | PR | 03/15/2013 | GW | 045-21713 | WPX Energy GM 331-12 | PR |
| 430276 | WELL | PR | 03/15/2013 | GW | 045-21714 | WPX Energy GM 31-12 | PR |
| 430277 | WELL | PR | 03/15/2013 | GW | 045-21715 | WPX Energy GM 41-12 | PR |

General Comment:

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|------------------------|-------|--|
| Type | WEEDS | | |
| Comment: | Continue weed control. | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--------------|-------|--|
| Type | SEPARATOR | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | | |
|--------------------|----------|--|--|-------|--|
| Type | WELLHEAD | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

| | | | | |
|-----------------------------------|------------------------------|--|--|-----------------|
| Equipment: | | | | corrective date |
| Type: Ancillary equipment | # 1 | | | |
| Comment: | Chemical container at wells. | | | |
| Corrective Action: | | | | Date: |
| Type: Bird Protectors | # 4 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heated Separator | # 6 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 6 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | | | Date: |

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | 300 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 256385 | Type: | WELL | API Number: | 045-07448 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 429917 | Type: | WELL | API Number: | 045-21682 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 430274 | Type: | WELL | API Number: | 045-21712 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 430275 | Type: | WELL | API Number: | 045-21713 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 430276 | Type: | WELL | API Number: | 045-21714 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 430277 | Type: | WELL | API Number: | 045-21715 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Berms | Pass | | | | | |
| Seeding | Pass | | | | | |
| Ditches | Pass | | | | | |
| Gravel | Pass | | | | | |
| Compaction | Pass | | | | | |
| Rip Rap | Pass | | | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| Check Dams | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401255458 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4120120 |