

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401261956

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH CO INC	Operator No: 27635	Phone Numbers Phone: (303) 830-7208 Mobile: (303) 916-4070
Address: PO BOX 1896		
City: EDWARDS State: CO Zip: 81632		
Contact Person: Jack McCartney Email: jack@mccartneyengineering.com		

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 10065 Initial Form 27 Document #: 401217756

PURPOSE INFORMATION

<input type="checkbox"/> 901.e. Sensitive Area Determination	<input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water
<input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure	<input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b.
<input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation	<input checked="" type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project
<input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste	<input type="checkbox"/> Rule 906.c.: Director request
<input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure	<input type="checkbox"/> Other

SITE INFORMATION Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: LOCATION	Facility ID: 319844	API #:	County Name: ADAMS
Facility Name: GINTHER-61S67W 20SWNW	Latitude: 39.951929	Longitude: -104.919602	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: SWNW	Sec: 20	Twp: 1S	Range: 67W Meridian: 6 Sensitive Area? No

SITE CONDITIONS

General soil type - USCS Classifications SC Most Sensitive Adjacent Land Use RESIDENTIAL

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Approx 550 cu yd soil	PID screenings, soil analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Initial soil and groundwater evaluation was completed adjacent to site facilities and ancillary equipment. Single location indicated contamination in both soil and groundwater. Additional soil borings and monitoring wells were completed adjacent to source to evaluate the extent of contamination. No remediation activities have yet been conducted.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Initial sampling completed. Samples were collected from TH-16 @ 15', TH-16 @ 25', SB-1 @ 10', SB-2 @ 10', SB-4 @ 13', SB-5 @ 15.5', SB-8 @ 14', SB-10 @ 9', and sampled for TVPH and BTEX.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Initial sampling completed. Samples were collected from TH-15, TH-16, and TH-21, and sampled for TVPH and BTEX. Monitoring wells TH-18 and TH-19 were dry at the time of the sampling.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 9
Number of soil samples exceeding 910-1 4
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 37

NA / ND

-- Highest concentration of TPH (mg/kg) 5189
NA Highest concentration of SAR
BTEX > 910-1 Yes
Vertical Extent > 910-1 (in feet) 15

Groundwater

Number of groundwater samples collected 2
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) 28'
Number of groundwater monitoring wells installed 6
Number of groundwater samples exceeding 910-1 1

-- Highest concentration of Benzene (µg/l) 55.4
-- Highest concentration of Toluene (µg/l) 4.56
-- Highest concentration of Ethylbenzene (µg/l) 62.4
-- Highest concentration of Xylene (µg/l) 295
NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) Volume of liquid waste (barrels)

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Source area soil will be excavated, transported from site, and properly disposed of at the Denver Regional Landfill South. Confirmational soil samples will be taken to ensure site soils are below COGCC standards.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Following soil excavation, confirmational soil samples will be taken to ensure site soils are below COGCC standards. Groundwater will be tested quarterly for four quarters to confirm groundwater has not been impacted.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Excavate and offsite disposal

_____ Chemical oxidation

If Yes: Estimated Volume (Cubic Yards) _____ 550

_____ Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or COGCC Facility ID # _____ 1005633

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

Yes _____ Other _____ four quarters of monitoring

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

The CTL/Thompson report dated January 9th, 2017, reported that groundwater sample collected from monitoring well TH-16 contained levels of Benzene above COGCC standards. Subsequent sampling of the TH-16 well, conducted by Western Environment and Ecology, Inc. on January 25th, 2017, indicated that all analyte concentrations were below COGCC standards. Groundwater will be sampled on a quarterly basis, for four quarters, to confirm that groundwater has not been impacted.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: Quarterly Semi-Annually Annually Other _____

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

N/A

Volume of E&P Waste (solid) in cubic yards 300

E&P waste (solid) description Stained petroleum contaminated soil with odor, elevated PID readings

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Front Range Landfill

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description N/A

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: N/A

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

Do all soils meet Table 910-1 standards? Yes

Does the previous reply indicate consideration of background concentrations? Yes

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? No

Does Groundwater meet Table 910-1 standards? Yes

Is additional groundwater monitoring to be conducted? Yes

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Backfilled with clean off site material. Location will not be reseeded since site will be graded in preparation for a housing development project.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim?

Final?

Did the Surface Owner approve the seed mix? No

If NO, does the seed mix comply with local soil conservation district recommendations? No

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 12/01/2016

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 12/13/2016

Date of commencement of Site Investigation. 12/13/2016

Date of completion of Site Investigation. 02/07/2017

REMEDIAL ACTION DATES

Date of commencement of Remediation. 03/15/2017

Date of completion of Remediation. 04/13/2017

SITE RECLAMATION DATES

Date of commencement of Reclamation. 04/13/2017

Date of completion of Reclamation. 04/13/2017

OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jack McCartney

Title: Agent

Submit Date: _____

Email: jack@mccartneyengineering.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 10065

COA Type

Description

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num

Name

401262712	OTHER
-----------	-------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)