

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2017

Submitted Date:

04/20/2017

Document Number:

672500493

FIELD INSPECTION FORM

Loc ID 449174 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10110
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC
Address: 1801 BROADWAY #500
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		cogccinspections@gwogco.com	All Inspections
Precup, Jim		james.precup@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449164	WELL	XX	02/09/2017		001-09993	Ocho LD 17-367HC	DG
449165	WELL	XX	02/09/2017		001-09994	Ocho LD 17-367HN	DG
449167	WELL	XX	02/09/2017		001-09996	Ocho LD 17-364HC	DG
449172	WELL	XX	02/09/2017		001-10001	Ocho LD 17-365HN	DG

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment

#

corrective date

Comment: APPROX 28' SOUND WALLS ON WEST, NORTH AND EAST SIDE OF LOCATION
DIRT BERM ON SW AND SOUTH OF LOCATION

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities			
Facility ID: <u>449164</u>	Type: <u>WELL</u>	API Number: <u>001-09993</u>	Status: <u>XX</u> Insp. Status: <u>DG</u>
Complaint			
Comment:			
Corrective Action:			Date:
Facility ID: <u>449165</u>	Type: <u>WELL</u>	API Number: <u>001-09994</u>	Status: <u>XX</u> Insp. Status: <u>DG</u>
Complaint			
Comment:	<p>Complaint #: 200441281</p> <p>Field Inspector Assigned: Jason E. Gomez</p> <p>Complaint Received:</p> <p style="margin-left: 20px;">Date: 4-6-2017 Time 1030 Hrs</p> <p>Contacted by Inspector:</p> <p style="margin-left: 20px;">Date: 4-6-2017 Time 1100 Hrs</p> <p>Well Number#: Location #: 449174</p> <p>Inspection Document #: 672500493</p> <p>Complainant: Melissa McGinnes Phone: 720-209-4800</p> <p>Address: 6051 E 160th Place, Brighton CO 80602</p> <p>Nature of complaint: Noise/Lights/Odors</p> <p>Field Inspector Actions:</p> <p>On 4-6-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a complaint at the residence of the complainants Melissa McGinnes 6051 E. 160th Pl, Brighton Colorado.</p> <p>I contacted the complainant who indicated she was experiencing a noise coming from the drilling rig located to the SE of her home, she described the noise has something she could hear like a low drowning sound but she said she could also fill the noise. She indicated the vibrations had caused thinks to shake off the walls in one of the bedrooms upstairs.</p> <p>I performed a complete site inspection of the location on 4-6-2017. At the time of inspection, I also performed a sound study approx. 25' from the SE corner of the complainant's home toward the drilling rig. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. All lighting on the rig were pointed down and toward the center of the location at the time of the inspection see inspections Doc#672500493 for attached sound study performed a complainants residence.</p> <p>Great Western Operating Company representative Scot Donato indicated a third party sound study would be conducted on 4-6-2017, and GW would supply the COGCC with those results.</p> <p>All information reviewed and site inspection as well as sound study information were submitted to the complaint specialist for further review.</p> <p>No violations of COGCC rules were observed at the time of the inspection.</p>		
Corrective Action:			Date:
Well Drilling			

Rig: Rig Name: PRECISION RIG 460 Pusher/Rig Manager: MARVIN
Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: YES Disposal Location: WASTE MANAGEMENT

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 449167 Type: WELL API Number: 001-09996 Status: XX Insp. Status: DG

Facility ID: 449172 Type: WELL API Number: 001-10001 Status: XX Insp. Status: DG

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Mulching	Pass					
Compaction	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Berms	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass					
Silt Fences	Pass					
Slope Roughening	Pass					
Ditches	Pass			Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500494	SOUND STUDY	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128568
672500495	Sound study Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128569
672500515	GREAT WESTERN SOUND STUDY RESULTS AFTER NEW MITTIAGATION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4128570