

# Inspection Photos

04/17/2017

Operator: Lilis Energy Inc #10495

Location ID: 322206

Inspection Doc. Number: 682501919

Elbert County, CO

SWSE Section 10 T6S R64W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Lilis Energy  
Location ID: 322206



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Lilis Energy  
Location ID: 322206



**Photo 2:** Photo taken from the west end of the location, facing south. Photo shows riser from flow/gathering system. Mr. Murphey from Lilis stated that Anadarko would be removing the lines on Wed. April 19<sup>th</sup>



**Photo 3:** Photo taken from the west end of the location, facing northeast. Photo shows related O&G facilities have been removed from the location. Reclamation in process.



Inspection Photos  
Operator: Lilis Energy  
Location ID: 322206



**Photo 4:** Photo taken from the west end of the location, facing east. Photo shows related O&G facilities have been removed from the location. Reclamation in process.



**Photo 5:** Photo taken from the west end of the location, facing southeast. Photo shows related O&G facilities have been removed from the location. Reclamation in process.

Inspection Photos  
Operator: Lilis Energy  
Location ID: 322206



**Photo 6:** Photo taken from the access road east of the location, facing west. Surface owner had stated interest in leaving a portion of this road. A 502.b variance to not perform reclamation on portions of the road desired by the surface owner will need to be submitted and approved.



**Photo 7:** Photo taken from the access road east of the location, facing southwest. Surface owner had stated interest in leaving a portion of this road. A 502.b variance to not perform reclamation on portions of the road desired by the surface owner will need to be submitted and approved.